

Table of Contents

Preface

Chapter 1: Technological Research

Surface Modification of Alumina Particles to Enhance Bonding Properties with Rubber and Resin in Grinding Tools

L. Čelko, V. Bednaříková, M. Remešová, M. Casas Luna, L. Klakurková, K. Zábranský, D. Holmý and J. Švejcar 3

Stabilizing the Microstructure of Additively Manufactured Low-C Co-28Cr-6Mo Alloy

M. Roudnická, J. Kubasek, J. Bigas and D. Vojtech 9

Production and Application of Magnesium Alloys Castings

L. Klakurková, M. Juliš, P. Gejdoš, J. Švejcar and J. Čileček 15

Correlating the Microstructure with the Mechanical Behaviour of Titanium Structures Produced by Robotic Assisted Deposition

A. Kashimbetova, S. Tkachenko, M. Remešová, A. Mata-Leija, P. Gejdoš, L. Čelko and E.B. Montúfar 22

Hardening of Rail Vehicle Axles

S. Němeček, K. Trojan, J. Čapek, N. Ganev, I. Černý and J. Kec 27

Tribotests of Valve Seats Made of ADI and Q - Cryo Cast Iron with Spheroidal Graphite

B. Skrbek and J. Mráz 32

Interaction of AZ91 Magnesium Alloy with Ceramic Shell during Investment Casting

P. Gejdoš, M. Juliš, L. Klakurková and M. Dyčka 37

Microstructure of Mo-La₂O₃ Composite Powder Prepared Using Two Different High Energy Ball Milling Systems

S. Tkachenko, L. Čelko, M. Remešová, V. Bednaříková, K. Dvořák, P. Komarov and K. Zábranský 43

Structure and Mechanical Properties of Welded Joints of Large Steel Forgings for Nuclear Power Plants of MIR 1200 Type

S. Hermanova, J. Kosňovská and L. Kander 49

The Evaluation of Ti-24Nb-8Ta-4Sn Alloy Prepared by 3D Printing

J. Krčil, V. Mára and J. Šimota 55

Influence of Forging Parameters on Microstructure and Properties of En AW-6082 Alloy

V. Mára, J. Horník and R. Bednář 61

Metallographic Evaluation of Ni-Cr Cold Spray Layers on the Tube

Z. Špirit, M. Chocholoušek and J. Brom 67

Laser Surface Hardening of Graphite Cast Iron

J. Horník, J. Krčil, V. Mára and A. Mores 74

Chapter 2: Materials Degradation

Damage and Fracture in Creep of a Cast B1914 Superalloy

M. Kvapilová, P. Král, J. Dvořák, K. Hrbáček, K. Kuchařová and V. Sklenička 83

Influence of Processing Technology on Creep Damage of Ultrafine-Grained Titanium

J. Dvořák, P. Král, A.G. Kadomtsev, V.I. Betekhtin, M.V. Narykova, M. Kvapilová and V. Sklenička 89

Effect of Graphite on Residual Lifetime of Superheater Tubes Made of Steel 16Mo3 after Creep Exposure

Š. Stejskalová, Z. Kuboň and G. Rožnovská 95

In Vitro Corrosion Study of Selected Laser Melted WE43 Magnesium Alloy in Hank's Balanced Salt Solution

V. Bednaříková, L. Klakurková, M. Remešová, M. Horynová, J. Suchý, D. Paloušek and L. Čelko 102

Creep Damage in Steam Pipelines and the Use of Metallography in Verifying the Possibilities of Testing

P. Mareš, J. Veselá and Z. Špirit 108

Chapter 3: Failure Analysis

Causes of Injection Mould Insert Block Damage	
Z. Pavloušková, L. Klakurková, M. Juliš, P. Gejdoš and J. Švejcar	117
Analysis of the Causes of Shaft Damage	
K. Zábranský, L. Klakurková, P. Gejdoš, M. Juliš and J. Švejcar	123
Analysis of Cracked Rail of the Crane of Type A120	
J. Kasl	129
Analysis of the Causes of Failure and Material Analysis of Components of the Screw Conveyor of a Coal Boiler for Steam Production	
J. Koc, E. Chvostová and J. Dlouhý	137

Chapter 4: Production Defects

Castings Defect Analyses	
M. Koukolíková	147
Analysis of the Causes of Increased Reject Rate in Connecting Rod Production	
P. Martínek and J. Vokáč	153
Analysis of Defects Associated with Manufacturing Keys for Brass Musical Instruments	
D. Bricin, J. Odehnal, A. Kříž and Z. Špirit	160
Analysis of a Damaged Drill Made from Hs 2-9-1-8 Steel	
V. Průcha, D. Bricin and J. Hájek	166

Chapter 5: Testing and Examination Methods

Application of Metallographic Investigation in Development of Sub-Sized Specimen Testing Techniques	
E. Chvostová, P. Konopík and P. Martínek	175
Characteristics of Metallographic Preparation of Heat Exchanger Austenitic Stainless Steels	
L. Pilsová, V. Mára, M. Svobodová and J. Horváth	181
Replicas Application in Non-Destructive Testing	
J. Veselá, P. Zahrádka and J. Matějčíček	187