

Table of Contents

Preface, Committee

Chapter 1: Degradation of Materials and Failure Analysis

Using Fractography for Determining of Technological Reasons of Defect and Brittle Fractures Occurrence in Steels	
J. Bezcny and I. Barenyi	3
The Analysis of Causes of Pressure Bottles Heads Destruction	
M. Svec and P. Kejzlar	15
Material Analysis of the Extended-Life Cobalt-Based Superalloys Used in the Manufacturing of Glass Tools	
P. Jonsta, I. Vlcková, Z. Jonsta and M. Król	21
Operational Degradation of Spheroidal Graphite Cast Iron EN GJS SiMo	
B. Skrbek	27
Structural Changes of Hot Work Tool Steel due to Heat load	
S. Krum, F. Peslova, J. Horník and M. Puchnin	34
Failure Mechanism of Yttria Stabilized Zirconia Atmospheric Plasma Sprayed Thermal Barrier Coatings Subjected to Calcia-Magnesia-Alumino-Silicate Environmental Attack	
L. Čelko, D. Jech, P. Komarov, M. Remešová, K. Dvořák, I. Šulák, B. Smetana and K. Obrlík	39
Failures of Engineering Structures Caused by Weld Imperfections	
V. Mára, J. Horník, E. Čížmárová, J. Krčil and P. Hájková	45
Fractographical Analysis of Screws Used for Truck Cab Holding	
P. Kejzlar, M. Svec and Z. Andršová	52
Causal Analysis of Damage of a Cover	
L. Páleníková, L. Klakurková, P. Gejdoš, M. Remešová, M. Juliš and L. Čelko	57
Analysis of Damage of Solder Joint of Heat Exchanger	
P. Gejdoš, L. Klakurková, M. Juliš, M. Horynová, L. Páleníková and J. Švejcar	63
Failure Analysis of Corrugated Hoses	
L. Klakurková, M. Horynová, M. Juliš, P. Gejdoš, L. Páleníková and J. Švejcar	68
The Influence of Microstructure on the Fracture Development in Engineering Parts	
J. Horník, E. Čížmárová, S. Krum, J. Krčil and V. Mára	74
Analysis of the Failure of the Engine Piston of the AlSi Alloy	
A. Podepřelová, V. Mareš and M. Kraus	80
Atypical Cases of Welded Structure Failures	
P. Bernasovský	86
Analysis of Causes of Fractures of Terminal Board Bolts	
J. Švejcar, L. Klakurková, M. Juliš, P. Gejdoš, M. Remešová and L. Páleníková	93

Chapter 2: Surface Defects and Surface Degradation

Application of Metallography in Solving of Manufacturing Defects of Galvanically Plated Polymers	
P. Podzimek, Z. Andršová and P. Kejzlar	101
The Use of Metallography for Examination of Causes of Surface Defects on Visual Parts	
Z. Andršová and P. Kejzlar	107
Influence of Microstructure on Machinability of Material and its Final Surface Quality	
Z. Pavloušková, M. Horynová, L. Klakurková, M. Juliš, P. Gejdoš and M. Remešová	112
Application of Metallographic Analysis Techniques for Detection and Identification of Spray Paint Defects	
M. Remešová, L. Klakurková, I. Ročňáková, L. Čelko, L. Páleníková and J. Kaiser	118
Influence of the Surface Condition of Specimens on the Size of Coherently Diffracting Domains	
J. Klečka, F. Lukáč and M. Dudr	124

Evaluation of Titanium Carbonitride Particles Using Image Analysis and Assessment of their Impact on Machinability

P. Martínek, J. Mišková and P. Sláma

130

Evaluation of Surface Degradation of Deoxidized AW-AlMg0.7Si Alloy

M. Horynová, M. Remešová, L. Klakurková, M. Juliš, P. Gejdoš and L. Páleníková

136

Metallographic Analysis of Filiform Corrosion

L. Hrabčáková and A. Mašlejová

142

Chapter 3: Degradation of Materials and Failure Analysis of Power Equipment

Analysis of Corrosion Attack on Kaplan Turbine Blades

J. Horník, P. Zuna, M. Zoubek, M. Svobodová and T. Chmela

149

Analysis of Pipeline Serviceability for Water Supply to Power Plant

E. Chvostová, P. Podaný and P. Konopík

156

Development of Creep Damage in Similar Weld Joints of P92 Steel Pipe

P. Král, V. Sklenička, K. Kuchařová, M. Svobodová, M. Kvapilová and J. Dvořák

162

Combining 3D Scanning with Standard Microscopy Methods for Assessment of Pitting Corrosion in Turbine Blades

P. Bublíková, V. Habrcetl, P. Mareš, R. Janura, A. Kobzová and Z. Vávrovcová

168

Failure of a Rotating Blade of a 200 MW Steam Turbine LP Rotor and Options for Eliminating other Similar Breakdowns

J. Kasl, M. Matějová and J. Mrštík

174

Quantitative Evaluation of Secondary Phases in a Weld Joint Made of COST F and FB2 Creep Resistant Steels

D. Jandová

183

The Analysis of Causes of the Damage of a Turbine Blade Made of Ti-6Al-4V Alloy

J. Krčil, J. Holec, J. Horník, P. Hájková, E. Čižmárová and V. Mára

189

Chapter 4: Analysis of Properties and Production Technologies of Coatings and Non-Ferrous Alloys

Al-Fe Chips Processed by High-Energy Ball Milling and Spark Plasma Sintering

V. Kučera, F. Prusa and D. Vojtěch

197

AZ31 and WE43 Alloys for Biomedical Applications

D. Dvorský, J. Kubásek and D. Vojtěch

205

Metallographic and Fractographic Evaluation of 3D-Printed Titanium Samples to Eliminate Unsatisfactory Mechanical Properties

M. Fousová, T. Stejskalova and D. Vojtěch

212

The Effect of Solution Treatment Temperature on Plastic Deformation and Fracture Mechanisms of Beta-Titanium Alloy

J. Malek, F. Hnilica, S. Bartáková and J. Veselý

218

The Role of Different Atmospheric Plasma Spray Parameters on Microstructure of Abradable AlSi-Polyester Coatings

D. Jech, L. Čelko, P. Komarov, J. Ziegelheim, Z. Česánek and J. Schubert

224

Investigations of Wettability of Wear Resistant Coatings Produced by Atmospheric Plasma Spraying

P. Komarov, L. Čelko, D. Jech, M. Papula, K. Slámečka, M. Horynová, L. Klakurková and J. Kaiser

230

Chapter 5: Analysis of Properties and Production Technologies of Steels

Effects of Heat Treatment on Microstructure of High-Strength Manganese-Silicon Steels

D. Bublíková, Š. Jeníček, K. Opatová and B. Mašek

239

Influence of Mechanical Stress at High Temperatures on the Properties of Steels Intended for the Manufacture of Fuel Cladding for Generation IV Reactors

Z. Špirit, M. Chocholoušek and M. Šíma

246

The Effect of Isothermal Hold Temperature on Microstructure and Mechanical Properties of TRIP Steel	
L. Kučerová, M. Bystrianský and J. Káňa	253
Effect of Chemical Composition and Heat Treatment Parameters on the Structure and Properties of Vanadis 23 and Vanadis 30 PM High-Speed Steels	
J. Sobotová, M. Kuřík and J. Lacza	258
Characterization of Microstructure of Hadfield Steel	
V. Průcha, Z. Jansa, J. Šimeček, O. Žďánský and A. Kříž	265
Analysis of Wrought Iron Metal Part of Cupola Construction in the Main Railway Station Plzeň from 1907	
M. Matějová, R. Fikrlová and J. Kasl	271