Table of Contents

Preface

Chapter 1: Cracks and Failures in Laminates and Hybrid Materials

Comparison of a Hybrid Pipe Design for Replacement of New and Corroded Steel Pipes Subjected to Transverse Impacts P. Townsend, A. Nevarez and M. Carboneras	3
An XFEM-Based Analysis on the Effect of Pre-Existing Cracks on the Woven GFRP with Central Side Edge Notch	J
D.R. Mohapatra, S. Behera and S. Mondal	9
The Application of a Hybrid Damage Modeling and Simulation Methodology to Composite Laminate Ultimate Strength Predictions G. Qi, H.H. Liu, I.Y. Kim and D. Wowk	15
Evaluation of a Fiberglass Patching Kit for Repairing Cracked Steel Plates via the PZT-SLDV Lamb Wave Technique N. Amiri and L.Y.L. Yu	21
Effect of Notch Shape and Size on the Mechanical Performance of Woven GFRP Laminate:	
A Numerical Investigation D.R. Mohapatra, S. Behera and S. Mondal	27
Chapter 2: Strength of Materials, Corrosion and Tribology	
Investigation of Pipe Failures in Sprinkler Systems: A Case Study I. Duma, E. Dobrin, G. Marginean, R. Faur, A. Afezolli, I.A. Perianu and R.N. Popescu	35
Characterization of a Low-Friction EPDM for Dynamic Sealings Applications: Tensile, Wear Behavior and Hot Water Resistance	45
D. Foltu, G.I. ooi, D.T. Pascal, I.D. Uţu and V.A. erban	45
3D-Printed Protective Button Covers for Technical Devices C. State and D.A. Predu	55
Investigation of the High Cycle Fatigue Behaviour of Aluminium Alloy Clinched Joints A. Shukurea, P.Z. Kovács and J. Lukács	65
The Research of the Cavitation Erosion Resistance of the Aluminium Alloy 2017 a Structure	
Obtained by WIG Remelted I. Bordeasu, A.N. Luca, R. Parmanche, C. Ghera, C.L. Salcianu, L.M. Micu, D. Ostoia, I. Duma and V.I. Safta	77
The Cavitation Behavior of the 6082 Alloy Aluminium Structure Obtained by WIG	
Remelted I. Bordeasu, R. Parmanche, C. Ghera, C.L. Salcianu, A.N. Sîrbu, N.A. Luca, I. Duma, S.T. Duma and C.E. Podoleanu	89
Review on Welding Criteria Related to Hydrogen Transport in Carbon Steel Pipelines Á. Pap, Á. Meilinger and M. Gáspár	101