

Table of Contents

| | |
|---|------------|
| Dedication, Author Information and Preface | |
| CHAPTER 1. INTRODUCTION | 1 |
| 1.1 Beginning of Metallurgy as a Science | 2 |
| 1.2 The Industrial Revolution and Metallurgy (1750-1850) | 3 |
| 1.3 Metal Science in late 19th and 20th Century | 4 |
| 1.4 Colonialism and its Influence on Metallurgical Progress:. 1.5 Epilogue. | 5 |
| References. Further Reading. | 6 |
| CHAPTER 2. EXTRACTIVE METALLURGY I: Pyrometallurgy. 2.1 Mineral Dressing (Mineral Beneficiation). | 7 |
| 2.2 Chemistry as a Precursor to Extractive Metallurgy. | 10 |
| 2.3 Basics of Pyrometallurgy | 11 |
| 2.4 Ironmaking. | 13 |
| 2.5 Steelmaking. | 20 |
| 2.6 Alloy Steels | 28 |
| 2.7 Copper | 30 |
| 2.8 Nickel | 33 |
| 2.9 Titanium | 35 |
| 2.10 Tin: 2.11 Lead: 2.12 Zinc. | 36 |
| 2.13 Platinum Group Precious Metals. | 37 |
| References. Further Reading | 39 |
| CHAPTER 3. EXTRACTIVE METALLURGY. Electro- and Hydro-Metallurgy. 3.1 Electrometallurgical Extraction of Metals | 41 |
| 3.2 Hydrometallurgical Extraction of Metals. | 47 |
| 3.3 Some Recent Developments | 58 |
| 3.4 Summary of the Historical Aspects of Hydrometallurgy : References | 60 |
| Further Reading | 61 |
| CHAPTER 4. PHYSICAL METALLURGY I: Structure of Metals and Alloys. | 63 |
| 4.1 Macrostructure. | 65 |
| 4.2 Microstructure and its Examination | 66 |
| 4.3 Crystal Structure | 75 |
| 4.4 Nanostructure | 82 |
| 4.5 Electronic Structure and Periodic Table | 83 |
| 4.6 Electronic Models for Transition Metals | 89 |
| 4.7 Bonding in Metal-like Refractory Compounds | 91 |
| 4.8 Structure of Liquid Metals | 95 |
| References | 97 |
| Further Reading | 99 |
| CHAPTER 5. PHYSICAL METALLURGY II: Phase Equilibria, Diffusion, Defects and Properties. 5.1 Phase Equilibria | 101 |
| 5.2 Alloy Formation and Stability | 108 |
| 5.3 Diffusion | 115 |
| 5.4 Defects in Crystals and Deformation | 119 |
| 5.5 Mechanical Properties | 138 |
| 5.6 Physical Properties | 158 |
| References | 167 |
| Further Reading | 172 |

| | |
|---|-----|
| CHAPTER 6. PHYSICAL METALLURGY III: Phase Transformation, Recrystallization and Grain Growth. 6.1 Liquid to Solid Transformation | 173 |
| 6.2 Solid to Solid Transformation | 175 |
| 6.3 Precipitation and Precipitation Hardening | 191 |
| 6.4 Recrystallization and Grain Growth | 200 |
| 6.5 Thermomechanical Treatment of Alloys (TMT) | 209 |
| References | 212 |
| Further Reading | 213 |
| CHAPTER 7 FUTURE TRENDS. | 215 |
| 7.1 Extractive Metallurgy | 216 |
| 7.2 Physical Metallurgy | 219 |
| 7.3 Computer Simulation | 229 |
| 7.4 Metals in Biosystems | 230 |
| 7.5 Future of Untapped Minerals and World Economy: 7.6 A Way towards Molecular Science | 232 |
| References | 233 |
| Further Reading | 236 |

Famous Metal Scientists in Pictorial