

# Table of Contents

## Preface, Committees, Organizers, Endorsers and Sponsors

## Chapter 1: Assessment and Conservation

|                                                                                                                                                                                                                           |     |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|
| <b>Experimental Values of Wood Strength in Bending between the 17<sup>th</sup> and the 18<sup>th</sup> Century</b><br>C. Tardini                                                                                          | 3   |
| <b>Considering the Role of Wood and Timber Roof in Persepolis Architecture</b><br>A. Davoodi and A. Davoodi                                                                                                               | 11  |
| <b>The Influence of Biological Factors on the Health of Timber Structures on 11<sup>th</sup> to 14<sup>th</sup> Century AD in Yazd</b><br>S.R. Moghaddam, S. Poormohamadi, M. Saffar and F. Esfahanipour                  | 19  |
| <b>Failures of the Listed Wooden Buildings in Istanbul</b><br>A.O. Kuruscu and G. Arun                                                                                                                                    | 26  |
| <b>A Symbolic Wooden Building in Istanbul: The Amcazade Huseyin Pasha Reception Hall/Divanhane</b><br>A. Erdem and Ö. Gürsel                                                                                              | 34  |
| <b>A Study on Timber Structural Elements of a Traditional Turkish House</b><br>O. Yilmaz Karaman and M. Tanac Zeren                                                                                                       | 42  |
| <b>Traditional Seismic Construction Technology of the Turkish House 'Konak', Concentration of the Case Study 'Saraclar Sehir House' in Safranbolu</b><br>A. Kerimcan                                                      | 50  |
| <b>Typical Failures, Seismic Behavior and Safety of the “<i>Bourbon System</i>” with Timber Framing</b><br>N. Ruggieri, G. Tampone and R. Zinno                                                                           | 58  |
| <b>Research and Development on the Database for Visualizing Invisible Parts of Wooden House in Japan</b><br>H. Sumikura, S. Matsumura and K. Fujita                                                                       | 66  |
| <b>Architectural Structural Survey of Groups of Traditional Timber Houses in South Nias, Indonesia</b><br>N. Sadaka, S. Hanazato, T. Hanazato, Y. Uekita, K. Nitto, K. Sato, K. Ono, S. Yoyok, P. Diananta and E. Pradipt | 74  |
| <b>Static and Thermohygroscopic Analysis of a New Typology of Timber Framed Structure in Dolomites</b><br>A. Polastri, S. Christofides and R. Tomasi                                                                      | 82  |
| <b>The Traditional Wooden House in Bucovina, a Model for Durability</b><br>C.G. Corduban and A. Polastri                                                                                                                  | 89  |
| <b>The Study of Timber Structures Based on <i>In Situ</i> Investigation</b><br>E. Zamperini                                                                                                                               | 97  |
| <b>How an Accurate Surface Observation Can Help in the Interpretation of an Ancient Timber Structure: The Example of the Valdese Church in Florence</b><br>N. Macchioni, M. Mannucci and A. Todorow                       | 105 |
| <b>XVIII Century Wooden Stretchers Structure Designed for Large Canvas and an Example of the Assessment Method</b><br>K. Górecka, M. Skłodowski, P. Pawłowski, J. Szpor and H. Arendarski                                 | 113 |
| <b>Antique Wooden Floor Construction Solutions and the Possibilities of Using them in Reconstructions</b><br>A. Rozanska, E. Sudol, J. Wierzbicki and A. Mazurek                                                          | 119 |
| <b>Wooden Boards Arches Roofs in Late Nineteenth-Century Industrial Architecture: Conservation Problems</b><br>M. Mattone                                                                                                 | 128 |

## Chapter 2: Timber Grading

|                                                                                                                                      |     |
|--------------------------------------------------------------------------------------------------------------------------------------|-----|
| <b><i>In Situ</i> Evaluation of the Reference Properties of Structural Timber Members. Use of Available Tools and Information</b>    |     |
| J.S. Machado                                                                                                                         | 137 |
| <b>Effects of Beetle Attack on the Bending and Compression Strength Properties of Pine Wood</b>                                      |     |
| H. Cruz and J.S. Machado                                                                                                             | 145 |
| <b>Prediction of Strength and Elasticity in Oak Beams on the Basis of External Wood Characteristics</b>                              |     |
| G. Riesco Muñoz and A. Remacha Gete                                                                                                  | 152 |
| <b>Mechanical and Fungicidal Properties of approximately 100 Years Old Oak, Beech and Spruce Wood Beams</b>                          |     |
| N. Thaler and M. Humar                                                                                                               | 159 |
| <b>Non-Destructive Tests and Bending Tests on Chestnut Structural Timber</b>                                                         |     |
| B. Faggiano, M.R. Grippa and B. Calderoni                                                                                            | 167 |
| <b>Effectiveness and Subjectivity of Visual Inspection as a Method to Assess Bending Stiffness and Strength of Chestnut Elements</b> |     |
| H.S. Sousa, J.M. Branco and P.B. Lourenço                                                                                            | 175 |
| <b>Juniper Structures in Western Mediterranean Vernacular Architecture: Ongoing Research</b>                                         |     |
| J.R. Ruiz-Checa and V. Cristini                                                                                                      | 183 |
| <b>Strength Class Prediction of Sardinia Grown Timber by Means of Non Destructive Parameters</b>                                     |     |
| G. Concu, B. de Nicolo, N. Trulli, M. Valdés and M. Fragiaco                                                                         | 191 |

### **Chapter 3: Assessment by Non-Destructive Methods and Survey Techniques**

|                                                                                                                             |     |
|-----------------------------------------------------------------------------------------------------------------------------|-----|
| <b>The Penetration Test to Evaluate Wood Decay after 20 Years Timber Structure Assessment Experience</b>                    |     |
| E. Giuriani, A. Marini, S. Cominelli and A. Gubana                                                                          | 201 |
| <b><i>In Situ</i> Compression Stress-Deformation Measurements along the Timber Depth Profile</b>                            |     |
| M. Drdácý and M. Kloiber                                                                                                    | 209 |
| <b><i>In Situ</i> Assessment Method of Wood Using Normalized Withdrawal Resistances of Metric-Screw Type Probes</b>         |     |
| N. Yamaguchi                                                                                                                | 217 |
| <b>Selected Methods of Diagnosis of Historic Timber Structures – Principles and Possibilities of Assessment</b>             |     |
| J. Jasieńko, T. Nowak and K. Hamrol                                                                                         | 225 |
| <b>Application of Non-Destructive Techniques in the Inspection of the Wooden Roof of Historic Buildings: A Case Study</b>   |     |
| M.J. Morales-Conde, C. Rodríguez-Liñán and P. Rubio de Hita                                                                 | 233 |
| <b>Investigation of Timber Members at the Marasyk Station in Prague by Non-Destructive Methods</b>                          |     |
| H. Hasnikova and P. Kuklík                                                                                                  | 243 |
| <b><i>In Situ</i> Non-Destructive Examination of Timber Elements</b>                                                        |     |
| J. Pošta, J. Dolejs and L. Vitek                                                                                            | 250 |
| <b>Nondestructive Evaluation of Timber Columns of a Capela Bridge in the State of São Paulo, Brazil</b>                     |     |
| F.S. Ferro, J.C. Pigozzo, D.H. de Almeida, F.H. Icimoto, L. Borges de Macedo, C. Calil Junior and F.A. Rocco Lahr           | 258 |
| <b>Experimental Investigations of Material Properties of Timber Utility Poles Using Various Material Testing Approaches</b> |     |
| R. Elsener, U. Dackermann, J.C. Li, B. Samali and K. Crews                                                                  | 265 |
| <b>Correlating Visual Grading with NTD Methods for Assessing Timber Condition in Historic Buildings</b>                     |     |
| V. Anagnostopoulou and A. Pournou                                                                                           | 273 |
| <b>Microwave Reflectometric Tool for Non-Destructive Assessment of Decay on Timber Structures</b>                           |     |
| N. Macchioni, M. Mannucci, R. Olmi, S. Palanti and C. Riminesi                                                              | 281 |

|                                                                                                                                                                                                                                                  |     |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|
| <b>Development of Radar Apparatus for Scanning of Wooden-Wall to Evaluate Inner Structure and Bio-Degradation Non-Destructively</b><br>Y. Fujii, Y. Fujiwara, Y. Yanase, T. Mori, T. Yoshimura, M. Nakajima, H. Tsusumi, M. Mori and H. Kurisaki | 289 |
| <b>Nondestructive Characterization of and Defect Detection in Timber and Wood</b><br>C. Sklarczyk, F. Porsch, B. Wolter, C. Boller and J.H. Kurz                                                                                                 | 295 |
| <b>Effect of Elastic Modulus and Poisson's Ratio on Guided Wave Dispersion Using Transversely Isotropic Material Modelling</b><br>M. Subhani, J.C. Li, H. Gravenkamp and B. Samali                                                               | 303 |
| <b>Ultrasonic Imaging of Defects in Building Elements Made from Timber</b><br>M. Krause, K. Mayer, P.K. Chinta and U. Effner                                                                                                                     | 312 |
| <b>Assessment of Timber Structures Using the X-Ray Technology</b><br>S. Franke, B. Franke and F. Scharmacher                                                                                                                                     | 321 |
| <b>Non Destructive Characterization of Wooden Members Using near Infrared Spectroscopy</b><br>A. Sandak, M. Riggio and J. Sandak                                                                                                                 | 328 |
| <b>Approaches to the Moisture Content Monitoring Intimber Elements: Development of a Resistive Method</b><br>T.A. N'Guyen, N. Angellier, S. Caré, L. Ulmet and F. Dubois                                                                         | 335 |
| <b>Development of a Methodology for the Visual Inspection of Engineered Wood Products and Metal Hangers in Residential Construction</b><br>J.R. Loferski, J.C. Bouldin and D.P. Hindman                                                          | 342 |
| <b>Terrestrial Laser Scanning and Settled Techniques: A Support to Detect Pathologies and Safety Conditions of Timber Structures</b><br>C. Bertolini-Cestari, F. Chiabrando, S. Invernizzi, T. Marzi and A. Spanò                                | 350 |

## **Chapter 4: Assessment by Testing and Modeling**

|                                                                                                                                                                                    |     |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|
| <b>Estimation of Load-Bearing Capacity and Stiffness of Timber Beams with Through-Thickness Cracks</b><br>A.Y. Naychuk                                                             | 361 |
| <b>Modulus of Elasticity and Bending Strength of Squared Timber with Wane of Spruce and Larch</b><br>T. Schrentewein                                                               | 369 |
| <b>Strength Properties of Chestnut Structural Timber with Wane</b><br>M. Brunetti, M. Nocetti and P. Burato                                                                        | 377 |
| <b>Non-Destructive and Semi-Destructive Test Methods for Strength Determination of Aged Wood</b><br>A. Kraler and W. Beikircher                                                    | 385 |
| <b>The Influence of Routed Grooves on the Bending Behavior of Old Timber Beams</b><br>A. Cavalli and M. Togni                                                                      | 393 |
| <b>Damage Assessment and Residual Service Life Estimation of Cracked Timber Beams</b><br>J.W.G. van de Kuilen and W. Gard                                                          | 402 |
| <b>Evaluation of the Load-Carrying Capacity in Bending of Large Cross Section "Pitch Pine" Beams in Standing Structures</b><br>M.C.T. Vázquez, A. Soilán Cañas and D. Lorenzo Fouz | 410 |
| <b>The SWORFISH Project Approach for Modeling Wood Material Modifications in Timber Structures</b><br>J. Sandak, A. Sandak, M. Riggio, I. Santoni and D. Pauliny                   | 418 |
| <b>Assessment of the Glue-Line Quality in Glued Laminated Timber Structures</b><br>B. Franke, F. Scharmacher and A. Müller                                                         | 424 |
| <b>Determination of the Stress Distribution in Timber Elements Reinforced with Self-Tapping Screws Using an Optical Metrology System</b><br>M. Ayoubi and M. Trautz                | 432 |
| <b>Characterization of Wood Fracture Using Optical Full Field Methods</b><br>O. Pop, F. Dubois, M. Méité and J. Absi                                                               | 440 |
| <b>Near Infrared Spectroscopy as a Tool for Estimation of Mechanical Stresses in Wood</b><br>J. Sandak, A. Sandak, D. Pauliny, V. Krasnoshlyk and O. Hagman                        | 448 |

|                                                                                                                                                                                                |     |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|
| <b>Stress Level Prediction in Axially-Loaded Timber Beams Using Resonance Frequency Analysis: A Pilot Study</b><br>T. Lechner, S. Laux and D. Sandin                                           | 454 |
| <b>A Vibration-Based Approach for the Estimation of the Loss of Composite Action in Timber Composite Systems</b><br>U. Dackermann, J.C. Li, R. Rijal and B. Samali                             | 462 |
| <b>An Evaluation of the Seismic Performance of a Traditional Timber Building in Istanbul, Based on the Material Deterioration, with the Finite Elements Method</b><br>H. Dişkaya and O. Ceylan | 470 |
| <b>Seismic Analysis of a 2-Storey Log House</b><br>J.M. Branco, P.B. Lourenço and C.A. Aranha                                                                                                  | 478 |
| <b>A New Method to Assess the Seismic Vulnerability of Existing Wood Frame Buildings</b><br>C. Loss, M. Piazza and D. Zonta                                                                    | 486 |
| <b>In-Plane Assessment of Existing Timber Diaphragms in URM Buildings via Quasi-Static and Dynamic <i>In Situ</i> Tests</b><br>I. Giongo, D. Dizhur, R. Tomasi and J.M. Ingham                 | 495 |
| <b>Shaking Table Test of 1/30 Scale Model of Palasport in Bologna with Timber Shell Roof Structure</b><br>L. Tashkov and L. Krstevska                                                          | 503 |
| <b>Study and Analysis of XIV Century Timber Built-Up Beams in Verona</b><br>G. Mirabella-Roberti and M. Bondanelli                                                                             | 511 |
| <b>Numerical Modelling of Historic Vaulted Timber Structures</b><br>C.F. Ferreira, D. D'Ayala, J.L. Fernandez Cabo and R. Díez                                                                 | 517 |
| <b>Assessment of the Realistic Stiffness and Capacity of the Connections in Quincha Frames to Develop Numerical Models</b><br>N. Quinn and D. D'Ayala                                          | 526 |

## **Chapter 5: Reinforcement and Treatment of Timber Elements**

|                                                                                                                                                                                                   |     |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|
| <b>Bending Tests on Natural Fiber Reinforced Fir Wooden Elements</b><br>A. Borri, M. Corradi and E. Speranzini                                                                                    | 537 |
| <b>Bamboo Reinforced Glulam Beams: An Alternative to CFRP Reinforced Glulam Beams</b><br>C. Echavarria, B. Echavarría and H. Cañola                                                               | 545 |
| <b>Analysis of Wood Laminated Beams Reinforced by Natural Fibres</b><br>N.T. Mascia and R.M. Mayer                                                                                                | 553 |
| <b>Moisture and Temperature Influence on Biocomposites-to-Timber Bonding</b><br>M.R. Valluzzi, F. Nardon, E. Garbin and M. Panizza                                                                | 561 |
| <b>Durability of Wooden Member Reinforced by Carbon-Fiber</b><br>T. Hojo                                                                                                                          | 569 |
| <b>Wood Glass-Fiber Reinforced Polyester (GFRP) Hybrid Cross-Section Used to Improve the Structural Behavior of Timber Beams</b><br>C.E. Lanivski and E. Decher                                   | 575 |
| <b>Restoration of Structural Timber Elements Using Epoxy Resin: Analysis of Mechanical Properties</b><br>M. da Silva Bertolini, L.B. de Macedo, D.H. de Almeida, F.H. Icimoto and F.A. Rocco Lahr | 582 |
| <b>The Repair of Timber Beams with Controlled-Debonding Steel Plates</b><br>G. Metelli, E. Giuriani and E. Marchina                                                                               | 588 |
| <b>Reinforcement of Timber Beams with Prestressed Wires</b><br>J.H.J. de Oliveira Negrão                                                                                                          | 596 |
| <b>Investigation on the Self-Tapping Screws Capability to Induce Internal Stress in Timber Elements</b><br>I. Giongo, M. Piazza and R. Tomasi                                                     | 604 |
| <b>Mechanical Evaluation of Timber Conservation Processes by Bending Tests</b><br>D.F. Henriques, L. Nunes and J. de Brito                                                                        | 612 |
| <b>Microwaves as a Remedial Treatment of Wood</b><br>A.M. Lluch, F. Vegas López-Manzanares, C. Mileto and M. Diodato                                                                              | 620 |

## Chapter 6: Strengthening of Connections

|                                                                                                                              |     |
|------------------------------------------------------------------------------------------------------------------------------|-----|
| <b>Lateral Resisting Experiment of Prestressed-Tube Bolted Connection for Post-and-Beam Timber Construction</b>              |     |
| M.J. He, Y. Zhao and R.L. Ma                                                                                                 | 631 |
| <b>Numerical Analysis of a Rigid Node of a Spatial Timber Frame Made of Structural Elements with Built-up Cross-Sections</b> |     |
| C.E. Lanivski, A. Secu and G.M. Atanasiu                                                                                     | 639 |
| <b>Novel Nail-Like Wood Connectors</b>                                                                                       |     |
| M. Riggio, D. Pauliny, J. Sandak and A. Sandak                                                                               | 647 |

## Chapter 7: Upgrading of Timber Structures

|                                                                                                                                      |     |
|--------------------------------------------------------------------------------------------------------------------------------------|-----|
| <b>Reinforcement of Timber Floors-Transversal Load Distribution on Timber-Concrete Systems</b>                                       |     |
| A.M.P.G. Dias, S.R.S. Monteiro and C.E.J. Martins                                                                                    | 657 |
| <b>Lateral Load Bearing Behavior of Timber-Concrete Composite Constructions</b>                                                      |     |
| H. Kieslich and K. Holschemacher                                                                                                     | 665 |
| <b>Ultra-Thin Topping Upgrades for Improved Serviceability Performance</b>                                                           |     |
| J. Skinner, R. Harris, K. Paine, P. Walker and J. Bregulla                                                                           | 673 |
| <b>Experimental Characterization of Timber Floors Strengthened by in-Plane Improvement Techniques</b>                                |     |
| M.R. Valluzzi, E. Garbin, M. dalla Benetta and C. Modena                                                                             | 682 |
| <b>Optimization of Mechanical and Acoustic Performance of Timber Floors</b>                                                          |     |
| M.R. Valluzzi, A. di Bella and E. Garbin                                                                                             | 690 |
| <b>Seismic Behaviour of Composite Panel Composed of Laminated Wood and Bearing Glass - Experimental Investigation</b>                |     |
| L. Krstevska, L. Tashkov, V. Rajčić and R. Zarnic                                                                                    | 698 |
| <b>Seismic Behaviour and Retrofitting of Timber Frame Walls</b>                                                                      |     |
| E. Poletti and G. Vasconcelos                                                                                                        | 706 |
| <b>A Development of the Visco-Elastic Damper for Timber Structure and a Suggestion of the Technological Design Assistance System</b> |     |
| K. Kohara, T. Nomura and K. Koumoto                                                                                                  | 714 |
| <b>Development of Wood-Based Multi-Layer Systems in Existing Building Stock</b>                                                      |     |
| A. Fadaei, W. Winter, D. Stefanoudakis and K. Hollinsky                                                                              | 722 |
| <b>Selected Solutions for Rehabilitation of Wooden Structures: Some Portuguese Case Studies</b>                                      |     |
| A.O. Feio, D. Félix, V.M. Cunha and J.S. Machado                                                                                     | 731 |
| <b>Repairing a Medieval Door</b>                                                                                                     |     |
| D. Yeomans, H. Harrison and A. Smith                                                                                                 | 739 |

## Chapter 8: Monitoring

|                                                                                                                                            |     |
|--------------------------------------------------------------------------------------------------------------------------------------------|-----|
| <b>Long Term Monitoring of Timber Bridges - Assessment and Results</b>                                                                     |     |
| B. Franke, S. Franke, A. Müller, M. Vogel, F. Scharmacher and T. Tannert                                                                   | 749 |
| <b>An On-Going Monitoring Project of a New Timber Structure</b>                                                                            |     |
| F. Lanata                                                                                                                                  | 757 |
| <b>The Echo (Jeka) Pavilion in Forest-Park Maksimir Zagreb - Restoration and Health Monitoring</b>                                         |     |
| M. Hasan, R. Despot, J. Trajković, A.O. Rapp, C. Brischke and C.R. Welzbacher                                                              | 765 |
| <b>12 Years of Structural Health Assessment and Maintenance for the Glulam Timber Structure of the Mormanno Traffic Bridge in Calabria</b> |     |
| G. Bignotti                                                                                                                                | 771 |
| <b>X-Lam Panels in Swimming-Pool Building – Monitoring the Environment and the Performance</b>                                             |     |
| L. Jorge and A.M.P.G. Dias                                                                                                                 | 779 |

|                                                                                                                                                     |     |
|-----------------------------------------------------------------------------------------------------------------------------------------------------|-----|
| <b>A Numerical Approach for the Hygro-Thermal Monitoring of Timber Structures under Environmental Conditions</b>                                    |     |
| A. Genoese, A. Genoese, S. Fortino and P. Hradil                                                                                                    | 786 |
| <b>A Multi Sensor Approach for Prediction of Weathering Effects on Exposed Timber Structures</b>                                                    |     |
| J. Sandak, A. Sandak, D. Pauliny, M. Riggio, S. Bonfa and S. Meglioli                                                                               | 794 |
| <b>Monitoring of Wood Decay by near Infrared Spectroscopy</b>                                                                                       |     |
| A. Sandak, S. Ferrari, J. Sandak, O. Allegretti, N. Terziev and M. Riggio                                                                           | 802 |
| <b>Influence of Fungi on the State of Preservation and on the Usage Prospects of Antique Wooden Floor from Manor Houses in South-Eastern Poland</b> |     |
| A. Boguslaw, A. Rozanska, A. Jankowska and J. Sandak                                                                                                | 810 |
| <b>Changes in Swelling and Water Absorption of Wood Degraded by Brown Rot Fungi</b>                                                                 |     |
| J. Frankl                                                                                                                                           | 818 |
| <b>Earthquake Response Monitoring and Structural Analysis of Traditional Japanese Timber Temple</b>                                                 |     |
| K. Fujita, E. Shin, A. Ibaraki and M. Sanuki                                                                                                        | 823 |

## Chapter 9: Learning from Case Studies

|                                                                                                                                                                                                               |     |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|
| <b>The Royal Palace of Naples: Diagnosis, Assessment and Structural Restoration of Complex Roofing Timber Structures</b>                                                                                      |     |
| B. Faggiano, M.R. Grippa and F.M. Mazzolani                                                                                                                                                                   | 831 |
| <b>Condition Assessment of the Timber Structures of a Century-Old Industrial Building Using a Nondestructive Inspection Procedure</b>                                                                         |     |
| X.P. Wang, M. Teder and J. Wacker                                                                                                                                                                             | 840 |
| <b>Diagnosis for the Conservation of Wooden Ceilings inside the Ducal Palace in Sabbioneta (Mantua, Italy)</b>                                                                                                |     |
| F. Augelli, A. Bordina and J. Migliavacca                                                                                                                                                                     | 849 |
| <b>The Structural Concept of the 16th Century Floors of the Ducal Palace in Sabbioneta (Mantua, Italy)</b>                                                                                                    |     |
| F. Augelli, V. Nicola, F. Petracco and L.C. Ronchi                                                                                                                                                            | 857 |
| <b>The Conservation and Strengthening Intervention on the Wooden Floors of the Ducal Palace in Sabbioneta (MN-Italy)</b>                                                                                      |     |
| F. Augelli                                                                                                                                                                                                    | 865 |
| <b>The Strengthening Design of the Wooden Floor Structures of the Ducal Palace in Sabbioneta (MN)-Italy</b>                                                                                                   |     |
| F. Augelli and C. Amigoni                                                                                                                                                                                     | 872 |
| <b>The Hidden Gem</b>                                                                                                                                                                                         |     |
| I. Andreescu, V.A. Gaivoronschi and M. Mosoarca                                                                                                                                                               | 880 |
| <b>Problems Relating to Assessment, Repair and Restoration of Wooden Roof Structures in Historic Buildings, as Exemplified by Two Case Studies in Southern Poland</b>                                         |     |
| D. Bajno, Ł. Bednarz and T. Nowak                                                                                                                                                                             | 888 |
| <b>Structural Analysis of Gothic Roof Trusses in View of their Conservation. Case Study of St. Paul's Cathedral, Liege (Belgium)</b>                                                                          |     |
| L. Debailleux                                                                                                                                                                                                 | 895 |
| <b>The Influence of Faulty 19<sup>th</sup> Century Technical Solutions on a Work of 18<sup>th</sup> Century Rafter Framing as Exemplified by Church in Nowy Kosciół in Lower-Silesia, Poland - Case Study</b> |     |
| K. Ałykow and M. Napiórkowska-Ałykow                                                                                                                                                                          | 903 |
| <b>The Wooden Roof of <i>Banesa e Skendulate</i> in Gjirokastra, Albania: The Role of the Diagnostic Test Campaign in the Structural Safety Evaluation</b>                                                    |     |
| S. Podestà, F. Pompejano and G. Stagno                                                                                                                                                                        | 911 |
| <b>Reconstruction of the Technical Museum in Zagreb</b>                                                                                                                                                       |     |
| V. Rajčić, D. Čizmar and M. Stepinac                                                                                                                                                                          | 919 |
| <b>Learning from Case Studies: Timber Tower of Gospić Cathedral and Traditional Timber Church</b>                                                                                                             |     |
| M. Stepinac, V. Rajčić and D. Čizmar                                                                                                                                                                          | 927 |
| <b>Wood Construction System of Traditional Edirne Houses</b>                                                                                                                                                  |     |
| I.S. Canitez and T. Canitez                                                                                                                                                                                   | 935 |

|                                                                                                                                                                                                                             |      |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|
| <b>An Evaluation of Restoration Practices of Traditional Wooden Houses in Edirne</b><br>T. Canitez and I.S. Canitez                                                                                                         | 943  |
| <b>Preservation of the Large Timber Roof of the Porta Nuova Railway Station in Torino</b><br>C. Bertolini-Cestari, S. Invernizzi, T. Marzi and S. Rolla                                                                     | 951  |
| <b>A Historical Large Span Timber Construction - Refurbishment of the Main Cupola of Vienna University of Technology</b><br>S. Jaksch, A. Fadaï and W. Winter                                                               | 959  |
| <b>The Ancient Timber Roofing Structures in Emilia-Romagna Region</b><br>A. Marzo, G. Marghella and M. Indirli                                                                                                              | 968  |
| <b>Investigation about the Decay of the Timber Structure of an Ancient Wine Cellar in La Rioja (Spain) and Sanitation Proposal</b><br>A. Lozano Martínez–Luengas, M. Guaita Fernández, D. Lorenzo Fouz and J. Benito Ayúcar | 976  |
| <b>Building for the Sea Safeguarding Ashore. Brigs, Ships and Peote: A Complex Conservation</b><br>S. Porello                                                                                                               | 983  |
| <b>Tramways, Draw Works and Flumes</b><br>D. Porter and R.W. Anthony                                                                                                                                                        | 990  |
| <b>Timber Structure Repair of an Emblematic Catalan Industrial Building with Wood Grafts and Epoxy Resins</b><br>M. Vilches Casals, V. Rodríguez Trujillo and C. Labèrnia Badia                                             | 998  |
| <b>A Comparison between Evaluation and Restoration Methods for Old Wooden Beam and Glued Laminated Timber</b><br>G. Cenci and S. Cenci                                                                                      | 1006 |
| <b>Structural Performance Analysis and Repair Design of Wenxing Lounge Bridge</b><br>Q. Chun and L.X. Sun                                                                                                                   | 1014 |
| <b>Diagnostic Evaluation of Insect Attack on Existing Timber Structures: A Review of some Case Studies</b><br>E. Feci, M. Mannucci and S. Palanti                                                                           | 1020 |
| <b>The World's Tallest Wooden Observatorion Tower. Design for Durability</b><br>M. Lackner and M. Vodicka                                                                                                                   | 1028 |

## Chapter 10: Codes and Guidelines

|                                                                                                                                                                                                                                                                  |      |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|
| <b>Assessment, Reinforcement and Monitoring of Timber Structures – COST FP1101</b><br>B. Kasal                                                                                                                                                                   | 1037 |
| <b>RILEM TC "Reinforcement of Timber Elements in Existing Structures"</b><br>T. Tannert, J.M. Branco and M. Riggio                                                                                                                                               | 1041 |
| <b>Developing an Understanding for Grading Timber in Existing Buildings</b><br>R.W. Anthony                                                                                                                                                                      | 1049 |
| <b>Structural Reliability of Spanish Softwoods. A New Answer for an Old Problem</b><br>M. Nevado                                                                                                                                                                 | 1056 |
| <b>A Peculiar Spanish Timber Floor, the "Revolton": A Diagnostic Example at the "Palacio del Marqués de Benicarló"</b><br>M. Diodato, N. Macchioni, M. Brunetti, B. Pizzo, M. Nocetti, P. Burato, L. Sozzi, E. Pecoraro, F. Vegas López-Manzanares and C. Mileto | 1064 |
| <b>Recommendations for Design in Preserving Historical Buildings with Wooden Structures' Roofs</b><br>Â. do Valle, N. Biscaglia Pereira and S. Castello Branco Nappi                                                                                             | 1072 |
| <b>Timber Roof Structures in Extreme Weather Conditions</b><br>T. Pazlar                                                                                                                                                                                         | 1080 |
| <b>Seismic Vulnerability of Timber Roof Structures: Classification Criteria</b><br>M.A. Parisi, C. Chesi and C. Tardini                                                                                                                                          | 1088 |
| <b>Evaluation of Health Conditions of Wooden Structures of the Former Slave Quarters of Farm Santa Maria do Monjolinho, Located in the State of São Paulo, Brazil</b><br>A.F. Campos, L.B. de Macedo, M.â.P. de Castroe Silva Bortolucci and F.A. Rocco Lahr     | 1096 |