

Table of Contents

Thick GaN Films Grown on Sapphire: Defects in Highly Mismatched Systems T. Paskova, E. Valcheva and B. Monemar	1
Novel Defect-Related Properties of Silicon S.M. Prokes and R.C. Cammarata	29
The Search for Tunnelling States in Bulk Silicon Disordered by Fast Neutron Irradiation M. Coeck and C. Laermans	47
Residual Shallow Donor- and Acceptor-Impurities in SSD- and LEC-Grown High-Purity InP Crystals E. Kubota, S. Yamada and K. Ando	67
Dislocations in Semiconductors: Core Structure and Mobility J.F. Justo	97
Analysis of Radiation-Induced Defects in InGaP Materials and Solar Cells A. Khan	107
A Perspective from Crystal Growth and Wafer Processing on the Properties of Intrinsic Point Defects in Silicon R.J. Falster and V.V. Voronkov	125
Copper Complexes in Silicon Crystals M. Nakamura	135
The Effect of Implant Temperature and Pre-Annealing on Defect Formation after Laser Thermal Processing H.B. Banisaukas, K.S. Jones, S. Talwar and D.C. Jacobson	145
X-Ray Topographic Analysis of Misfit Dislocation Distribution in InGaAs and GeSi/Si Partially Relaxed Heterostructures C. Ferrari	153
Processing-Induced Defects in Epitaxially Grown p- and n-Type SiGe M. Mamor, F.D. Auret and S.A. Goodman	161
Quantitative Measurements of Vacancy Defects in High-Energy Ion-Implanted Si R. Kalyanaraman, T.E. Haynes, V.C. Venezia, D.C. Jacobson, H.J.L. Gossmann and C.S. Rafferty	177
Positron Annihilation Studies of Vacancy Defects in Crystalline and Amorphous Si G. Amarendra	189
Modelling Cu Diffusion into a Ta Barrier C.L. Liu	219
Transmission Electron Microscopy of the Configuration of Cracks and the Defect Structure near to Cracks in Si H. Saka and Suprijadi	225
Study of the Localized Modes in ZnSe:P for the Elucidation of Site Symmetry N. Sankar and K. Ramachandran	247
EBIC/XPS Study of Antimony Equilibrium Segregation at the Germanium Surface N. Tabet	259
Abstracts	1