## Durability and Failure in Engineering Materials

## **Table of Contents**

Fracture Strength of Resin/Metal Bonds R.J. McConnell, C. Moriarty and D. Taylor	1
A Study of the Thermal Shock Resistance of Glazed and Unglazed Ceramic Tableware P. Lyons, D. McKernan and A.D. Kennedy	9
Environmental Effects on Crack Growth Rates in Glass Fibre Reinforced Polyester D. O'Grady, M. Buggy and C. Birkinshaw	17
The Oxidation of a Silicon Nitride Ceramic Densified with Mixed Magnesia/Neodymia Additions	
M.J. Pomeroy and S. Hampshire	25
The Durability of Materials used in Orthopaedic Implants D. Taylor and B. McCormack	35
Effects of Processing Conditions and Microstructural Development on Strength of Silicon Nitride Densified with Magnesia/Neodymia Mixed Additives B. Saruhan and S. Hampshire	45
The Effect of Zirconia Second Phase Additions on the Strength and Fracture Toughness of a Mullite Ceramic	
J. Moran, T. Kelly, S. McKenna Lawlor and J.A. Slevin	57
Toughness of Ultrafine WC-Co Composites from Hertzian and Palmqvist Indentation Testing	69
M.T. Laugier	69
<b>Palmqvist Indentation Crack Analyses for Toughness Determination in WC-Co Composites</b> M.T. Laugier	77
Material Evaluation and Assessment with the PEAT Microscope L. McDonnell, M.E. Woods and E.M. Cashell	85
Expert System Blackboard Concept Applied to Mechanical Analysis and Design J.F. McNamara and R.A. O'Sullivan	97
Numerical Solution of Anisotropic Linear Elastic Fracture Problems - Edge Function Methods	
J.J. Grannell and J. Dwyer	115
Instrumentation in a Creep Laboratory P.D. Normoyle, T. Murphy, P.J. O'Reilly and D.M.R. Taplin	121
An Integrity Assessment of Two H.P. Turbine Rotors Straightened by Hot-Spotting	
C.T. Jones	133