

# Table of Contents

## Preface, Organizing Committees and Acknowledgement

## I. Steels

<b>Various Approaches to Accelerated Carbide Spheroidization of 54SiCr Steel</b> L. Kučerová, H. Jirková and B. Mašek	3
<b>Identification of Carbides in Sub-Zero Treated Vanadis 6 Ledeburitic Steel</b> J. Ptačinová, M. Dománková, M. Hudáková, P. Jurčí and P. Bílek	9
<b>Influence of Heat Treatment Conditions on Properties of High-Speed P/M Steel Vanadis 30</b> J. Sobotová, M. Kuřík and J. Cejp	17
<b>Microstructure of Tool Steel X37CrMoV5 after Cryogenic Treatment and its Effect on Wear Resistance</b> D. Jandová, P. Šuchmann and J. Nižňanská	23
<b>Influence of Annealing Temperature and Time on the Mechanical Properties of Selected Steels for Heavy Forgings</b> J. Horník, P. Zuna, J. Málek, T. Jetmar, J. Kasl, M. Matějová and F. Jandoš	38
<b>Effect of Sample Thickness on Slab Surface Zone Toughness in IF and Microalloyed Steels</b> M. Longauerová, M. Fedorová, P. Bekeč, J. Duška, M. Hurakova, S. Longauer and J. Konrádyová	47

## II. Alloys

<b>Novel Trends in the Development of Metallic Materials for Medical Implants</b> D. Vojtěch, J. Kubásek, J. Čapek and I. Pospišilová	59
<b>Materialographic Analysis of MAR M-247 Superalloy</b> P. Jonšta, I. Vlčková, Z. Jonšta and B. Podhorná	66
<b>The Influence of Ge on the Properties of Mg Alloys</b> J. Šerák, T. Kovalčík, D. Vojtech and P. Novák	72
<b>The Influence of Oxygen on Mechanical Properties of Ti35Nb6Ta Alloy</b> F. Hnilica, J. Malek and J. Veselý	79
<b>Effect of Al Content and Heat Treatment on Microstructure of ZnAlCu Alloys</b> M. Longauerová, M. Glogovský and M. Vojtko	85

## III. Surface Treatment and Powder Metallurgy

<b>Dependence of NiTi Alloy Microstructure on the Conditions of Powder Metallurgy Production</b> P. Novák, H. Moravec, J. Vystrčil, J. Adámek, J. Kopeček and T. Kubatík	95
<b>Structure of Nanocrystalline Nickel Prepared by Powder Metallurgy</b> A. Michalcová, P. Svobodová, I. Marek, D. Vojtech and T. Kubatík	102
<b>Utilization of Light Microscopy for the Evaluation of Fracture Toughness of Cemented Carbides</b> Z. Špirit and A. Kříž	108
<b>Corrosion Resistance of Inconel 625 and Austenitic Steel M41 after Laser Claddings</b> S. Němeček, L. Fiedler and P. Fišerová	115
<b>Microstructure of Cr<sub>2</sub>N-11Ag Nanocomposite Thin Film Deposited on Vanadis 6 Tool Steel</b> P. Bílek, P. Jurčí, L. Caplovic, M. Hudáková and J. Ptacínová	121

## VI. Welding and Creep Resistant Materials

<b>Structure Analyses of Experimental Welds Designed for Repair Welding of VVER 1000 Pressure Vessel</b> M. Matějová, D. Jandová and J. Kasl	131
---	-----

<b>Laser Welding of High-Strength CP Steels: Dissimilar Welds</b>	141
J. Kašpar and Š. Němeček	
<b>Heterogeneous Welded Joints (T23-T92; 15CH1M1F-P91)</b>	147
P. Ducháček and J. Janovec	
<b>Influence of Microstructural Changes in Creep Resistant Steel after Long-Term Creep Tests on the Shape of the Polarization Curves</b>	153
J. Sladká, D. Jandová and E. Chvostová	
<b>Material Degradation of Steam Pipe Elbow after Long-Term Exposure</b>	162
L. Pekařová and Z. Kuboň	

## V. Methods of Research and Analyze

<b>Metallographic Evaluation of Surface Integrity</b>	
A. Kříž	173
<b>Application of Stereological Relations for the Characterization of Porous Materials via Microscopic Image Analysis</b>	
T. Uhlířová, E. Gregorová and W. Pabst	180
<b>Porosity Quantification of Cast Aluminium Alloys on Machined Surfaces Using Metallography and Eddy-Currents</b>	
B. Skrbek	188
<b>Metallographic and Acoustic Analyses of Sintered Sliding Layers</b>	
B. Skrbek	195

## IV. Failure Analysis

<b>Assessment of the Causes of Indicated Defects in forgings</b>	
J. Švejcar, L. Klakurková, K. Stránský, Z. Spotz and L. Čelko	205
<b>Analysis of Coupling Segment of Belt Conveyor</b>	
L. Klakurková, L. Čelko, M. Juliš, D. Jech and J. Švejcar	210
<b>Chain Segment Analysis</b>	
D. Jech, L. Klakurková, L. Čelko, P. Doležal and J. Švejcar	216
<b>Analysis of Cracked Spring Washer for Sleeper-Rail Joints</b>	
Z. Pavloušková, O. Man, M. Horynová, L. Čelko and J. Švejcar	222
<b>Defects in Tool Steels for Dies</b>	
J. Mišková, P. Martínek and P. Podaný	228
<b>Failure Analysis of a 20 MW Turbine Rotor</b>	
J. Kasl	235
<b>Detection of Cracks in the Production of Shafts</b>	
J. Holec, M. Morávek and J. Cejp	243
<b>Corrosion Resistance of Casings for Metal Detectors in Food Industry Made of Cr-Ni Stainless Steel</b>	
P. Martínek, J. Mišková and P. Podaný	248