

Table of Contents

Preface and Committees and Sponsors

Keynote Presentations

A Full-Field Stress Based Damage Assessment Approach for <i>In Situ</i> Inspection of Composite Structures J.M. Dulieu-Barton, R.K. Fruehmann and S. Quinn	3
Damage Assessment of Structures Using only Post-Damage Vibration Measurements C. Surace	11

Chapter 1: Composite Materials

Simulation of Impact Damage in Foam-Based Sandwich Composites D.S. Feng and F. Aymerich	25
Identification of Composite Delamination Using the Krawtchouk Moment Descriptor W.Z. Wang, D.Z. Wang, J.E. Mottershead and G. Lampeas	33
Effect of Plate Curvature on Blast Response of Carbon/Epoxy Composite V.A. Phadnis, P. Kumar, A. Shukla, A. Roy and V.V. Silberschmidt	41
Ultrasonically Assisted Drilling: Machining towards Improved Structural Integrity in Carbon/Epoxy Composites V.A. Phadnis, F. Makhadmeh, A. Roy and V.V. Silberschmidt	49
Changes in the Dynamic Behaviour of Carbon Fibre Reinforced Polymer Elements with Increasing Damage R. Capozucca and V. Maccioni	56
A Simulation-Based Monitoring of a Composite Plate Using an Integrated Vibration Measurement System P. Kostka, A. Filippatos, R. Höhne and W. Hufenbach	64
Damage Detection in Composite Materials Using Airborne Acoustics M.R. Pearson, M.J. Eaton, E. Szigeti, R. Pullin, A. Clarke, R. Burguete and C.A. Featherston	72
Automated Damage Detection in Composite Components Using Acoustic Emission R. Pullin, M.R. Pearson, M.J. Eaton, C.A. Featherston, K.M. Holford and A. Clarke	80
Consumed Fatigue Life Assessment of Composite Material Structures by Optical Surface Roughness Inspection P. Zuluaga-Ramírez, M. Frövel, R. Restrepo, R. Trallero, R. Atienza, J.M. Pintado, T. Belenguer and F. Salazar	88
Investigation of Nonlinear Vibro-Acoustic Wave Modulation Mechanisms in Composite Laminates Ł. Pieczonka, W.J. Staszewski and T. Uhl	96
Investigation of Dynamic Fracture Behavior of Graphite L. Peroni, M. Scapin, F. Carra and N. Mariani	103
Numerical Procedures for Damage Mechanisms Analysis in CFRP Composites F. Caputo, D.F. Gennaro, G. Lamanna, A. Lefons and A. Riccio	111
Mechanical Characterization of Hybrid (Organic-Inorganic) Geopolymers G. Lamanna, A. Soprano, F. Bollino and M. Catauro	119
Non-Destructive Investigation of Glass Fiber Reinforced Composites via Magnetic Resonance Imaging F. Wetterling, K.H. Mok, C. McGoldrick and B. Basu	126

Chapter 2: Damage in Civil Infrastructure

Development of a Remote Collaborative Visual Inspection System for Road Condition Assessment A. Miyamoto	135
--	-----

Polymeric Bearings – A New Base Isolation System to Reduce Structural Damage during Earthquakes	
T. Falborski and R. Jankowski	143
Symptom-Based Reliability Analysis and Remaining Service Life Prediction of Deteriorating RC Structures	
T.L. Huang and H.P. Chen	151
Finite Element Analysis for Structural Performance of Offshore Platforms under Environmental Loads	
S.E. Abdel Raheem and E.M.A. Abdel Aal	159
Identifying Dynamic Characteristics of a Short-Span Viaduct from Vehicle-Induced Vibrations Considering Different Pavement and Parapet Conditions	
K.C. Chang and C.W. Kim	167
NDT Data Fusion for the Enhancement of Defect Visualization in Concrete	
P. Cotič, E. Niederleithinger, V. Bosiljkov and Z. Jagličić	175
Monitoring of Changes in Bridge Response Using Weigh-In-Motion Systems	
D. Cantero, A. González and B. Basu	183
Innovative Strategy to Reduce the Seismic Vulnerability of a RC Existing Building: Assessment and Retrofitting	
D. Cancellara, F. de Angelis, M. Modano and V. Pasquino	191
Impact of Road Profile when Detecting a Localised Damage from Bridge Acceleration Response to a Moving Vehicle	
D. Hester and A. González	199
Probabilistic Modelling of the Deterioration of Reinforced Concrete Port Infrastructure	
T.C.K. Molyneaux, D.W. Law, F. Collins, F. Blin, R. Zou and K. Siamphukdee	207
Investigating the Use of Moving Force Identification Theory in Bridge Damage Detection	
C.H. Carey, E.J. O'Brien and J. Keenahan	215
Testing and Monitoring for a Large Scale Truss Bridge Using Long-Gauge Fiber Optic Sensors	
C.F. Wan, W. Hong, Z.S. Wu and T. Sato	223
Evaluation of Timber-Concrete Floor Performance under Occupant-Induced Vibrations Using Continuous Monitoring	
P. Omenzetter, V. Kohli and Y. Desgeorges	230
The Concept of Buildings Stability Monitoring and Damage Diagnostics	
V. Volkovas	238
The Impact of the Gigacycle Fatigue on Steel Bridges	
C.S. Bandara and R. Dissanayake	246
Damage Variation in Highway Bridge Piers for Rehabilitation with Different Reinforced Options	
C.M. Gómez-Soberón, B. Olmos-Navarrete, M. Jara-Díaz and J.M. Jara-Guerrero	254
A Parametric Study of a Drive by Bridge Inspection System Based on the Morlet Wavelet	
P.J. McGetrick and C.W. Kim	262
On the Seismic Performance of Elevated Water Tanks and their Control Using TLDs	
A.D. Ghosh, S. Bhattacharyya and A. Roy	270
Sustainable Design of Smart Health Facilities in Seismically Prone Areas	
C. Rainieri and G. Fabbrocino	278
Rapid Assessment of Natural Periods of Large Short-Period Civil Engineering Structures	
V. Pakrashi, B. Basu and K. Ryan	286
Seismic Damage Assessment of Regular Gravity Design Buildings	
C. Negulescu, K.K. Wijesundara and E. Foerster	294
Re-Anchorage of a Ruptured Tendon in Bonded Post-Tensioned Concrete Beams: Model Validation	
A.O. Abdelatif, J.S. Owen and M.F.M. Hussein	302
Post-Earthquake Damage Assessment Process and Problems in Turkey – A Case Study in Van Province	
D.G. Yilmaz, J. von Meding and G.K. Erk	310
Pedestrian Timber Bridges: Experimental Investigation and Modelling	
S. Casciati, L. Faravelli and D. Bortoluzzi	319

The Sensitivity of Vibration Characteristics of Reinforced Concrete Beams under Incremental Static and Cyclic Loading	
W.I. Hamad, J.S. Owen and M.F.M. Hussein	327
PolyVinylidene Fluoride (PVDF) Material Based Energy Harvesting from Train and Damaged Bridge Interaction	
P. Cahill, N. Jackson, A. Mathewson and V. Pakrashi	335
Dynamic Testing and Long Term Monitoring of a Twelve Span Viaduct	
X.H. Chen, P. Omenzetter and S. Beskhyroun	342
Control Performance Evaluation to Avoid Pounding of Bridges	
G.H. Heo, C.G. Kim, S.G. Jeon and E.J. Kim	350
Assessment of Structural Reliability of Bridge Beams Based on Measured Symptoms	
A. Quattrone, E. Matta, L. Zanotti Fragonara, R. Ceravolo and A. de Stefano	358
A Seismic Reliability Assessment of Reinforced Concrete Integral Bridges Subject to Corrosion	
M.N. Choine, A. O'Connor and J.E. Padgett	366
Diagnosis of Damage in a Steel Tank with Self-Supported Roof through Numerical Analysis	
D. Buracki, M. Wójcik and R. Jankowski	374
Evaluating the Structural Capacity of Concrete Elements through <i>In Situ</i> Instrumentation	
D. Byrne and J. Giggins	382
Non-Destructive Tests for the Structural Assessment of a Historical Bridge over the Tua River	
I. Valente, L.F. Ramos, K. Vasquez, P. Guimarães and P.B. Lourenço	390
Experimental Analysis of Bending and Axial Crush Behaviour of Single Hat Longitudinal Rail	
N.A. Husain and C.L. Pang	398
On the Assessment of Fatigue Damage in Railway Bridges	
D.W. O'Dwyer	406

Chapter 3: Damage in Machineries

Failure Stress in Notched Paper Sheets	
C.A. Mora Santos, O. Susarrey Huerta, V. Flores Lara, J. Bedolla Hernández and M.A. Mendoza Nuñez	417
Spectral-Based Fatigue Assessment of Ball Grid Arrays under Aerospace Vibratory Environment	
L.B. Fekih, G. Kouroussis and O. Verlinden	425
Detection of Bearing Spalling Faults Using IAS Monitoring System - Experimental Studies on the Influence of Operating and Environmental Parameters	
A. Bourdon, H. André and D. Rémond	433
Stochastic Modeling of Time Series with Application to Local Damage Detection in Rotating Machinery	
J. Obuchowski, A. Wylomanska and R. Zimroz	441
Gear Fault Diagnosis Using Synchro-Squeezing Transform Based Feature Analysis	
B. Hazra and S. Narasimhan	449
Modal Strain Energy Based Damage Detection Applied to a Full Scale Composite Helicopter Blade	
F.L.M. dos Santos, B. Peeters, H. van der Auweraer and L.C. Sandoval Góes	457
Utilizing Data from a Sensorless AC Variable Speed Drive for Detecting Mechanical Misalignments	
S. Abusaad, A. Benghozzi, Y.M. Shao, F.S. Gu and A. Ball	465
Bearings Fault Detection in Gas Compressor in Presence of High Level of Non-Gaussian Impulsive Noise	
T. Barszcz, R. Zimroz, J. Urbanek, A. Jabłoński and W. Bartelmus	473
Concordia Transform-Based Current Analysis for Induction Motor Diagnosis	
J.J. Wang, R.X. Gao and R.Q. Yan	481
The Fault Characteristics of Planetary Gear System with Tooth Breakage	
Y. Gui, Q.K. Han, Z. Li, Z.K. Peng and F.L. Chu	489

Spalling Size Evaluation of Rolling Element Bearing Using Acoustic Emission A.B. Ming, Z.Y. Qin, W. Zhang and F.L. Chu	497
--	-----

Chapter 4: Renewable Energy

In-Service Measurement of the Small Wind Turbine Test Stand for Structural Health Monitoring M. Luczak, S. Manzato, M. Kahsin, D. Potok, M. Rozycki, D. Sporna and B. Peeters	507
Rapid Assembly of Multifunctional Thin Film Sensors for Wind Turbine Blade Monitoring L.P. Mortensen, D.H. Ryu, Y.J. Zhao and K.J. Loh	515
Virtual Structural Monitoring of Wind Turbines Using Operational Modal Analysis Techniques E. di Lorenzo, S. Manzato, B. Peeters and H. van der Auweraer	523
Non-Linear Aeroelastic Stability of Wind Turbines Z.L. Zhang, M.T. Sichani, J. Li, J.B. Chen and S.R.K. Nielsen	531
Fatigue Analysis of Offshore Wind Turbines on Fixed Support Structures N. Alati, V. Nava, G. Failla, F. Arena and A. Santini	539
Advanced Tools for Damage Detection in Wind Turbines I. Antoniadou, N. Dervilis, R.J. Barthorpe, G. Manson and K. Worden	547
Damage Identification in a Laboratory Offshore Wind Turbine Demonstrator A. Gómez González, E. Zugasti and J. Anduaga	555
Dynamic Responses of a Scaled Tension Leg Platform, Wind Turbine Support Structure in a Wave Tank J. Murphy, R. O'Shea, K. O'Sullivan and V. Pakrashi	563
Simulation of the Stochastic Wave Loads Using a Physical Modeling Approach W.F. Liu, M.T. Sichani, S.R.K. Nielsen, Y.B. Peng, J.B. Chen and J. Li	571
Failure Analysis of Wind Turbines by Probability Density Evolution Method M.T. Sichani, S.R.K. Nielsen, W.F. Liu, J.B. Chen, J. Li and Y.B. Peng	579
Generalized Stochastic Constraint TARMA Models for In-Operation Identification of Wind Turbine Non-Stationary Dynamics L.D. Avendaño-Valencia and S.D. Fassois	587
Numerical Modeling to Aid in the Structural Health Monitoring of Wave Energy Converters W. Finnegan and J. Goggins	595
Modal Analysis for Crack Detection in Small Wind Turbine Blades M.D. Ulriksen, J.F. Skov, K.A. Dickow, P.H. Kirkegaard and L. Damkilde	603
Dynamic Stall on Rotating Airfoils: A Look at the N-Sequence Data from the NREL Phase VI Experiment S. Guntur, N.N. Sørensen and S. Schreck	611
Feature Selection - Extraction Methods Based on PCA and Mutual Information to Improve Damage Detection Problem in Offshore Wind Turbines E. Zugasti, L.E. Mujica, J. Anduaga and F. Martínez	620
On Structural Health Monitoring of Wind Turbine Blades J.F. Skov, M.D. Ulriksen, K.A. Dickow, P.H. Kirkegaard and L. Damkilde	628
On the Modeling of Spar-Type Floating Offshore Wind Turbines V.N. Dinh and B. Basu	636
Offshore and Onshore Wind Energy Conversion: The Potential of a Novel Multiple-Generator Drivetrain N. Goudarzi and W.D. Zhu	644
Monitoring Changes in the Soil and Foundation Characteristics of an Offshore Wind Turbine Using Automated Operational Modal Analysis G. de Sitter, W. Weitjens, M. El-Kafafy and C. Devriendt	652
Active Tuned Mass Damper Control of Wind Turbine Nacelle/Tower Vibrations with Damaged Foundations B. Fitzgerald and B. Basu	660
Active Blade Pitch Control for Straight Bladed Darrieus Vertical Axis Wind Turbine of New Design P.D. Chougule, S.R.K. Nielsen and B. Basu	668

Low-Cost Tower Root Fatigue Load Estimation for Structural Health Monitoring of Grouted Connections in Offshore Wind Turbines N. Perišić and P.H. Kirkegaard	676
--	-----

Chapter 5: Sensing and Sensors

Damage Detection Using Electromechanical Impedance Technique Combined with Scanning Laser Vibrometry S. Opoka, P. Malinowski, T. Wandowski, L. Skarbek and W. Ostachowicz	687
Analyzing the Strain Sensing Response of Photoactive Thin Films Using Absorption Spectroscopy D.H. Ryu and K.J. Loh	695
Application of Piezo Sensors in EMI and Guided Wave Techniques P. Malinowski, L. Skarbek and W. Ostachowicz	702
Characterization of CFRP Using Laser Vibrometry P. Malinowski, T. Wandowski and W. Ostachowicz	710
Impact Localisation in Orthotropic Plates Using Flexural Wave Intensity Measurement C.R. Halkyard and P. Masson	718
Sensors and Methods for Blade Damage Operational Assessment in Low-Pressure Steam Turbine Stages P. Procházka and F. Vaněk	726
Interpolation Damage Detection Method on a Suspension Bridge Model: Influence of Sensors Disturbances M. Domaneschi, M.P. Limongelli and L. Martinelli	734
Compressive Sensing for Structural Damage Detection of Reinforced Concrete Structures M. Jayawardhana, X.Q. Zhu, R. Liyanapathirana and U. Gunawardana	742
Sensor Performance Assessment Based on a Physical Model and Impedance Measurements I. Buethe and C.P. Fritzen	751
The Status of Research on Self-Sensing Properties of CNT-Cement Based Composites and Prospective Applications to SHM C. Rainieri, C. Pannunzio, Y. Song, G. Fabbrocino, M.J. Schulz and V. Shanov	759
Vision-Based Sensing in Dynamic Tests F. Casciati, S. Casciati and L.J. Wu	767
Wireless Sensor Network for Helicopter Rotor Blade Vibration Monitoring: Requirements Definition and Technological Aspects A. Sanchez Ramirez, K. Das, R. Loendersloot, T. Tinga and P. Havinga	775
An Analysis of the Effectiveness of Application of Rotation Rate Sensors in Non Destructive Damage Evaluation S. Kokot, Z. Zembaty and P. Bobra	783
How Many Vibration Response Sensors for Damage Detection & Localization on a Structural Topology? An Experimental Exploratory Study C.S. Sakaris, J.S. Sakellariou and S.D. Fassois	791
Investigating the Flexural Behaviour of Foams at High Strain Rate Using Optical Measurement Techniques D.A. Crump and J.M. Dulieu-Barton	799
Design and Validation of Embedded Piezoelectric Transducers for Damage Detection Applications in Concrete Structures G. Karaiskos, S. Flawinne, J.Y. Sener and A. Deraemaeker	805
Sensor Fusion on Structural Monitoring Data Analysis: Application to a Cable-Stayed Bridge D. Zonta, F. Bruschetta, R. Zandonini, M. Pozzi, M. Wang, B. Glisic, D. Inaudi, D. Posenato and Y. Zhao	812

Chapter 6: Signal Processing

Damage Detection of a Substructure Based on Response Reconstruction in Frequency Domain J. Li, S.S. Law and Y. Ding	823
---	-----

Integrating Singular Spectrum Analysis with Damage Detection of Structure S.S. Law and K. Liu	831
A Two-Stage Scheme for Plate Damage Identification Based on Lock-in Thermography and Dynamic Analysis H.Y. Gao, X.L. Guo, P.J. Hou, C.W. Wu and H.J. Ouyang	839
Damage Detection in a Glass Plate Using Outlier Analysis K. Yang, K. Worden and J.A. Rongong	847
Numerical Studies on Wavelet-Based Crack Detection Based on Velocity Response of a Beam Subjecting to Moving Load W.W. Zhang, J. Geng, Z.L. Zhao and Z.H. Wang	854
Two Dimensional Damage Localization Using the Interpolation Method M.P. Limongelli	860
Spatial Filter for Operational Deflection Shape Component Filtration J. Wójcicki, K. Mendrok and T. Uhl	868
Damage Detection in Nonlinear Structures Using Discrete-Time Volterra Series S.B. Shiki, V. Lopes and S. da Silva	876
Cointegration and the Empirical Mode Decomposition for the Analysis of Diagnostic Data I. Antoniadou, E.J. Cross and K. Worden	884
Application of the Hilbert-Huang Transform for Identification of Changes in Boundary Conditions of a Bridge Using Vibration Data due to Traffic A. González and H. Aied	892
Estimating Vibration-Fatigue-Life on Experimentally Acquired Data M. Mrsnik, J. Slavič and M. Boltezar	900
Damage Detection Using Cointegration Technique and Wavelet Analysis of the Post-Cointegrated Lamb Waves P.B. Dao and W.J. Staszewski	908
Damage Detection Using Principal Component Analysis Based on Wavelet Ridges F. Gharibnezhad, L.E. Mujica, J. Rodellar and C.P. Fritzen	916
Non-Linear Vibro-Acoustic Wave Modulations - Analysis of Different Types of Low-Frequency Excitation A. Klepka, W.J. Staszewski, K. Dziedziech and F. Aymerich	924
Monitoring Dynamic Structural Tests Using Image Deblurring Techniques D.M.J. McCarthy, J.H. Chandler and A. Palmeri	932
Extension of Lamb Waves Defect Location Techniques to the Case of Low Power Excitation by Compressing Chirped Interrogating Pulses L. de Marchi, N. Testoni, A. Perelli and A. Marzani	940
Unscented Kalman Filter for Non-Linear Identification of a New Prototype of Bidirectional Tuned Vibration Absorber: A Numerical Investigation E. Matta, R. Ceravolo, A. de Stefano, A. Quattrone and L. Zanolli Fragonara	948
Imaging and Characterizing Structural Defects through the Estimation of Local Dispersion Curves E.B. Flynn, G.S. Jarmer, S.Y. Chong and J.R. Lee	956
Engine Assembly Quality Defect Inspection Based on EMD-Envelope Spectra W.J. Ye and Y.M. Shao	962
Real-Time Autonomous Structural Change Detection Onboard Wireless Sensor Platforms R.S. Carbajo, E.S. Carbajo, B. Basu and C. McGoldrick	970
Novel Approaches for Processing of Multi-Channels NDT Signals for Damage Detection in Conveyor Belts with Steel Cords R. Blazej, L. Jurdiak and R. Zimroz	978
Use of LU Decomposition of Modal Flexibility in Structural Damage Detection: Numerical Validation Y.H. An and J.P. Ou	986

Chapter 7: Structural Health and Condition Monitoring

Real Human Hearing: Damage Detection and Monitoring of the Treatment Effectiveness E.L. Ovchinnikov, V.V. Ivanov, Y.V. Ovchinnikova and P.V. Peskov	997
---	-----

Ultrasonic Guided Wave Tomography for Damage Detection in Harsh Environment J.D. Hua, L. Zeng, J. Lin and W. Shi	1005
Detection and Quantitative Assessment of Damages in Beam Structures Using Frequency and Stiffness Changes G.R. Gillich and Z.I. Praisach	1013
Crack Location in Beams Using Wavelet Analysis M. Solís, M. Algaba and P. Galvín	1021
On the Use of Low and High Cycle Fatigue Damage Models M. Abdel Wahab, I. Hilmy and R. Hojjati-Talemi	1029
Synthetic Aperture Focusing Technique for Detecting Transverse Cracks in Austenitic and Dissimilar Welds J. Prager, C. Höhne and M.U. Rahman	1036
On the Integration of Real-Time Diagnosis and Prognosis for Scheduled Maintenance Optimization C. Sbarufatti, A. Manes and M. Giglio	1044
Smart Structural Health Monitoring Validated on a Simple Plate under Compressive Loading C. Viechtbauer, K.U. Schröder and M. Schagerl	1052
Analytical Modelling of Bond Strength Degradation due to Reinforcement Corrosion J. Nepal, H.P. Chen and A.M. Alani	1060
Investigation of Dynamic Response of a Railway Bridge Equipped with a Tailored SHM System P. Kołakowski, A. Mroz, D. Sala, P. Pawłowski, K. Sekuła and A. Świercz	1068
Influence of Physical Parameters and Operating Conditions for Structural Integrity of Mechanical System Subjected to Squeal Noise K. Soobbarayen, S. Besset and J.J. Sinou	1076
Operational Deflection Shape for Crack Detection in Structures E. Asnaashari and J.K. Sinha	1085
Vibration-Based Structural Health Monitoring of a Simulated Beam with a Breathing Crack J. Kullaa, K. Santaoja and A. Eymery	1093
Magnetic NDT and Computer Modeling of Steel Rope Deterioration in Suspended Bridges A. Vorontsov, A. Zhirnov and D. Sukhorukov	1101
Comparative Study of Robust Novelty Detection Techniques N. Dervilis, R.J. Barthorpe and K. Worden	1109
Vibration Methods of Damage Detection in Initially Symmetric Structures V. Beresnevich and V. Jevstignejev	1116
Anaerobic Corrosion of Reinforcement R. O'Donovan, B.D. O'Rourke, K.D. Ruane and J.J. Murphy	1124
Experimental Investigation on Improving Electromechanical Impedance Based Damage Detection by Temperature Compensation T. Siebel and M. Lilov	1132
Comparison of Full Field Strain Distributions to Predicted Strain Distributions from Limited Sets of Measured Data for SHM Applications P. Avitabile, E. Harvey and J. Ruddock	1140
Uncertainty Modeling and Quantification for Structural Health Monitoring Features Derived from Frequency Response Estimation Z. Mao and M.D. Todd	1148
Strength Assessment of Deteriorated OHL Conductors and Earth Wires Based on Non-Destructive Testing V. Volokhovskiy, V. Sukhorukov and V. Tzukanov	1156
Defect Detection Using Pulse Phase Thermography - Repeatability and Reliability of Data R.C. Waugh, J.M. Dulieu-Barton and S. Quinn	1164
Experimental Testing of a Cross-Entropy Algorithm to Detect Damage A. González, E. Covián, M. Casero and J. Cooper	1170
RFID Based Sensing for Structural Health Monitoring M. Lisowski and T. Uhl	1178
Energy Correlated Damage Indices in Fatigue Crack Extent Quantification K. Dragan, M. Dziendzikowski, S. Klimaszewski, S. Klysz and A. Kurnyta	1186

The Dynamic Behaviour of a Buried Water Pipe and its Effect on Leak Location Using Acoustic Methods	
F. de Almeida, P. Joseph, M. Brennan, S. Whitfield and S. Dray	1194
Wavespeed Measurement in Buried Water Distribution Pipes and its Significance in Leak Location	
M. Brennan, F. de Almeida, P. Joseph, S. Dray and S. Whitfield	1202
Assessment of Historic Structures Based on GPR, Ultrasound, and Impact-Echo Data Fusion	
G. Safont, A. Salazar, L. Vergara, A. Vidal and A. Gonzalez	1210
Structural Health Monitoring under Varying Environmental Conditions Using Wavelets	
A. Tjirkallis, A. Kyprianou and G. Vessiaris	1218
Damage Assessment in a Cracked Fiber-Reinforced Cantilever Beam Using Wavelet-Kurtosis Techniques	
L. Montanari, B. Basu, A. Spagnoli and B. Broderick	1226
Modelling of Piezo-Bond Structure System for Structural Health Monitoring Using EMI Technique	
S.K. Bhalla and S. Moharana	1234
Damage Detection of Shear Connectors Based on Power Spectral Density Transmissibility	
J. Li and H. Hao	1241
Multi-Technique Approach for the Assessment of Historical Masonry Constructions	
F.M. Fernandes, L.F. Ramos, E. Manning, J. Ferreira and P. Mendes	1249
Application of Multiple Objective Particle Swarm Optimisation in the Design of Damaged Offshore Mooring Systems	
Z. Wang, T.J. McCarthy and M.N. Sheikh	1257
A Compensation Method for Environmental Influences on Passive Lamb Wave Based Impact Evaluation for CFRP	
K.J. Schubert and A.S. Herrmann	1265
Detection and Localisation of Structural Damage Based on the Polynomial Annihilation Edge Detection: An Experimental Verification	
C. Surace, M. Mattone and M. Gherlone	1273