

Table of Contents

Preface

Chapter 1: Metallurgy and Processing of Steel and Alloys

The Interaction of the Components of the Injected Two-Phase Flow with Hot Metal during Injection Desulphurization in the Ladle I. Manachyn, V. Yeliseiev, V. Kysliakov, M. Rybalchenko and V. Petrusha	3
Thermodynamic Study and Predicted Amorphization Composition Range of the Co-Ni-Ti Liquid Alloys M. Turchanin, P. Agraval, A. Vodopyanova and V. Korsun	11
Energy Implications of Switching to Surfactant-Modified Concentrate in Iron Ore Pellet Induration V.V. Kukhar, Y. Chuprinov, I. Navolniev and E. Belan	21
Features of the Formation of the Structure of Welded Joints of Structural Steels during Underwater Welding with Filler Wire 12X18N9T Using External Electromagnetic Influence S. Maksimov, O.A. Prilipko, O.M. Berdnikova, O. Kushnarova and I. Alekseenko	33
Axial Fatigue of PBF-LB Ti6Al4V: Process and Surface Effects T. Rautio, M. Hietala, M. Jaskari, A. Mustakangas and A. Järvenpää	43
Fatigue Resistance of PBF-Lb IN625-RAM2 Alloy A. Järvenpää, I. Poutiainen, M. Jaskari, A. Mustakangas, T. Rautio and A.S. Hamada	51
Sustainable Roller Burnishing: Effects on Surface Roughness and Power Consumption in Additively Manufactured AlSi10Mg Alloy Ö.F. Sağdıç, M. Yücel, A. Aydın, N. Alkan, Y.F. Yapan and A. Uysal	59
Characterization of the Interface between WAAM-Deposited Carbon Steel and S355 Structural Steel Plate M. Hietala, T. Rautio, M. Jaskari, M. Keskitalo, J. Pääkkilä and A. Järvenpää	67
Effects of Ball Milling Time on CoCrFeNiTi High Entropy Sintered Alloys A. Fujii and A. Nishimoto	75

Chapter 2: Fatigue, Fractography and Failure Analysis

Fracture Surface Morphology and Roughness of Ti-Scaffold Filaments J. Pokluda, J. Escherová and M. Kianicova	83
Metal Dusting Failure in an Aniline Processing Plant Z. Kuboň, J. Kosňovská and G. Rožnovská	91
Fractography and Microstructural Analysis of Fatigue Crack Propagation in Beta-Annealed Ti6Al4V Alloy after Fatigue Test J. Belan, M. Uhrčík, M. Slezák and V. Chvalníková	99
Influence of High-Pressure Hydrogen on Tensile Properties of Pipeline Steels Evaluated by Autoclave <i>In Situ</i> SSRT J. Kander and G. Rožnovská	107
Fracture Mechanisms of Aluminum Alloy Caused by Fatigue Tests M. Uhrčík, P. Palček, J. Belan, V. Chvalníková, M. Slezák and L. Šikyňa	113