

# Table of Contents

## Preface

## Chapter 1: Protection and Restoration of Wooden Structures and Elements

<b>Application of Thermal Analysis for the Quantification of Mineralization in Surface Wooden Layers</b> T. Majstříková, P. Mec and J. Daňková	3
<b>Verification of Mineral Particles Deposition in Wooden Construction Elements by Thermal Analysis</b> T. Majstříková, J. Daňková and M. Škopcová	9
<b>Impact of Thermal and Moisture Expansion on Design of Wooden Facade Elements for Retrofitting of Buildings</b> B. Nečasová, P. Liška and M. Novotný	15
<b>The Comparison of Moisture Balance of Diffusion-Open and Diffusion-Closed Structure of a Building Envelope</b> K.E. Hellová, A. Struhárová and M. Kostecká	23
<b>Validation of Orthotropic Parameters of Timber by Means of Elastic Layer Theory</b> V. Hlavata, P. Kuklík and J. Vanerek	29

## Chapter 2: Monitoring, Reliability Assessment and Restoration of Concrete Structures and Elements

<b>Influence of Coarse Aggregate Grain Size on Frost Resistance of Concrete</b> D. Kocáb, T. Vymazal, B. Kucharczyková, P. Daněk, R. Halamová and P. Hanuš	37
<b>Methods Appropriate for Determination of the Prescribed Reinforcement of the Elements of Reinforced Concrete Structures - Nowadays Used Methods</b> O. Anton, T. Komárková and V. Heřmánková	41
<b>Monitoring of Selected Physical and Thermal Properties of Lightweight Concrete Based on Recycled Foam Plastics</b> A. Daubnerová and S. Unčík	46
<b>Monitoring of the Setting and early Hardening with Ultrasonic Waves</b> I. Rozsypalová, O. Karel, B. Kucharczyková, D. Kocáb and R. Halamová	51
<b>Non-Destructive Schmidt Rebound Hammer Evaluation of the Degradation of Concrete Exposed to Elevated Temperatures</b> I. Rozsypalová, P. Daněk, J. Sachr and O. Karel	55
<b>Textile Concrete in Adverse Conditions</b> T. Bittner, M. Kostecká, P. Pokorný, M. Vokáč and P. Bouška	59
<b>The Classification of Cracks Recorded during the Cyclic Loading of the Reinforced Concrete Beam by Acoustic Emission Method</b> L. Topolář, L. Pazdera, M. Hoduláková, K. Mikulášek, P. Orolin and O. Roth	66
<b>Use of Computed Tomography for the Evaluation of Autoclaved Aerated Concrete Structure</b> M. Lédl, P. Šebestová, V. Černý and R. Drochytka	70
<b>Conclusive Determination of Compliance with the Prescribed Reinforcement Elements of Concrete Structures - The Appropriate Methods and their Capabilities</b> O. Anton, T. Komárková and V. Heřmánková	76
<b>Application of Acoustic Emission Method and Impact Echo Method to Structural Rehabilitation</b> L. Pazdera, R. Dvořák, M. Hoduláková, L. Topolář, K. Mikulášek, J. Smutný and Z. Chobola	81
<b>Comparison of Ultrasonic Methods for Thermally Damaged Concrete Nondestructive Testing</b> M. Matysík, L. Carbol, Z. Chobola, R. Dvořák and I. Plšková	86

<b>Thermophysical Properties of Cement Based Composites with Addition of Plastic Fibers and Horse Manure</b> G. Pavlendová, P. Šín, J. Lukovičová and M. Kopčok	92
<b>Utilization of Fly Ash Contaminated by SNCR Flue Gas Denitrification into Polymer Epoxy Anchor</b> T. Žlebek, J. Hodul and R. Drochytka	98
<b>Lightweight Mortars Based on Expanded Perlite</b> V. Pavlík and J. Bisaha	104

## **Chapter 3: Surface Treatment, Moisture Protection and Thermal Insulation**

<b>Study of Hydrophobic Modification of Ceramic Elements</b> V. Novák and J. Zach	121
<b>Influence of Hydrophobic Agent on Rheological Behavior of Historical Plaster. Part 1: Initial Hardening Time</b> R. Pernicová	127
<b>Influence of Hydrophobic Agent on Rheological Behavior of Historical Plaster. Part 2: External Temperature</b> R. Pernicová	133
<b>Glass Micro-Bubbles as Additional Thermal Insulation/Shielding for Translucent and Non-Transparent Materials</b> F. Novotný, L. Prokopová and D. Bošová	140
<b>Issue of Epoxy-Based Coatings System Crystallization and Effect of Partial Crystallinity on Mechanical Parameters</b> M. Vyhnánková, J. Hodul and J. Bydžovský	147
<b>Methodology for Determination of the Requirement of Repair of External Facades of ETICS due to the Occurrence of Microorganisms</b> P. Ryparová and L. Balík	153
<b>Mechanical Fracture Parameters of Extruded Polystyrene</b> H. Šimonová, B. Kucharczyková and Z. Keršner	160

## **Chapter 4: Reliability Assessment and Restoration of Architectural Structures**

<b>Contribution to Solving the Damp Masonry of the Romanesque Church</b> E. Burgetová, K. Michalová and M. Violo	167
<b>The Church Microclimate Monitoring</b> L. Kudrnáčová and L. Balík	177
<b>Failures on Historical Buildings as a Result of Deterioration of the Foundations and the Subsoil</b> J. Záleský and K. Kovářová	185
<b>Rehabilitation of Historical Drainage and Ventilation System in the Prague Castle Area</b> E. Burgetová, K. Michalová and L. Balík	191
<b>The Plecník's Reconstructed Footbridge at Prague Castle, Eleven Years after</b> V. Vacek and J. Kolísko	197
<b>Technology of 3D Print in Field of Renovation of Architectural Structures and Historical Buildings</b> M. Utěšená and R. Pernicová	201
<b>Degradation of Foundations and Foundation's Structures Achilles' Heel of the All Saints Church from the Broumov Group</b> P. Kuklík, E. Susanti and M.V. Valek	207
<b>Reliability Assessment of Lateral Halls of Svijanska Arena</b> J. Marková, K. Jung and V. Bureš	215