

Table of Contents

Preface

Chapter 1: Restoration of Architectural and Structural Elements from Wood and Timber

Considering the Role of Wood and Timber Roof in Persepolis Architecture A. Davoodi and A. Davoodi	3
Non-Destructive and Minimal-Invasive Status Determination and Heritage Friendly Remediation of the Wooden Structures of Bothmer Castle G. Haroske, U. Diederichs and V. Petranek	11
Failures of the Listed Wooden Buildings in Istanbul A.O. Kuruscu and G. Arun	18
Wooden Boards Arches Roofs in Late Nineteenth-Century Industrial Architecture: Conservation Problems M. Mattone	26
Wooden Buildings by the Fire Damaged of Toxic Gases on Personnel Evacuation Influences C.S. Lin, C.C. Yu, T.C. Chen, S.C. Wang and L.Y. Shen	33
Thermal Degradation of a Wood Painting Support from XIXth Century R.A. Cristache, A.V. Sandu, V. Vasilache and I. Sandu	40
Selected Solutions for Rehabilitation of Wooden Structures: Some Portuguese Case Studies A.O. Feio, D. Félix, V.M. Cunha and J.S. Machado	45
Recommendations for Design in Preserving Historical Buildings with Wooden Structures' Roofs	
A. do Valle, N. Biscaglia Pereira and S. Castello Branco Nappi Evaluation of Health Conditions of Wooden Structures of the Former Slave Quarters of	53
Farm Santa Maria do Monjolinho, Located in the State of São Paulo, Brazil A.F. Campos, L.B. de Macedo, M.â.P. de Castroe Silva Bortolucci and F.A. Rocco Lahr	61
The Influence of Biological Factors on the Health of Timber Structures on 11 th to 14 th Century AD in Yazd S.R. Moghaddam, S. Poormohamadi, M. Saffar and F. Esfahanipour	67
Review of Timber Structure Reinforcement Research for the Huizhou Ancient Architecture X.Y. Xiong and Z.Y. Su	74
Bending Test on Composite Timber-Steel-Concrete Floor Equipped with Innovative Collar Connectors	
A. Marzo, M.R. Grippa, B. Faggiano and F.M. Mazzolani	79
Complex Covering Timber Structures in Monumental Buildings: A Study Case M.R. Grippa, A. Marzo, B. Faggiano and F.M. Mazzolani	85
Rehabilitation of Timber Structures and Seismic Vulnerability: A Case Study M.A. Parisi, M. Riggio, C. Tardini and M. Piazza	91
The Royal Palace of Naples: Diagnosis, Assessment and Structural Restoration of Complex Roofing Timber Structures B. Faggiano, M.R. Grippa and F.M. Mazzolani	97
Learning from Case Studies: Timber Tower of Gospic Cathedral and Traditional Timber Church	
M. Stepinac, V. Rajčić and D. Čizmar	106
The Ancient Reinforced Beams as Model of Consolidation an Example in the Palazzo Pallavicino in Cremona (Italy) A. Grimoldi	114
In Situ Non-Destructive Examination of Timber Elements J. Pošta, J. Dolejs and L. Vítek	119

Chapter 2: Conventional and Unconventional Materials in the Practice of Restoration

The Utilization of Waste Aluminosilicate to Prepare Cement Composite with Thermal Insulating and Drying Effect A. Brenek, V. Vaclavik, J. Valíček, T. Dvorsky, J. Daxner, M. Bendová and V. Šimíček	129
Bacterial Induced Cementation Processes and Mycelium Panel Growth from Agricultural Waste	
E. Mayoral González and I. González Diez	135
Chemical and Physical Processes in the Synthesis of Romancement from Clay and Dolomite I. Kirilovica, L. Krage, I. Vitina and S. Igaune-Blumberga	143
Influence of Ox Blood on Water Absorption of and Chloride Penetration into Concrete J.G. Xu, T.J. Zhao, P. Zhang and R. Jiang	147
Research on Paste-Like Impregnation Coatings for Protecting Concrete W.J. Gu, Z.Y. Cheng, Y. Li and J.K. Liu	152
Restoration of Historic Concrete Structures with Modern Materials - A Case Study A. Gypser, A. Flohr and A. Osburg	157
The Use of Composites in Architectural Restoration: Some Critical Considerations on the Theoretical Implications E. Coïsson and F. Ottoni	165
Structural Performance of Old Composite Floors Made up of Wrought Iron Joists and Masonry Vaults	100
N. Gattesco and L. Macorini	173
Analysis of Different Building Materials Used in Heritage Protected Areas in North China X.Y. Zhang, Y.Q. Sun, X. Lan and J.M. Bai	185
Development of Thermal Insulation, Capillary Active Plasters Suitable for Historical Buildings	
J. Hroudová, J. Zach and M. Sedlmajer	192
On Thermo-Hydro-Mechanical (THM) Fatigue Damage of Historical Stone Buildings D. Hoxha, N. Belayachi and D.P. Do	196
Hydrophobized Lime Plasters as Protective Surface in Wet Rooms in Monument Preservation B. Wolff	202
Hygrothermal Behaviour of Newly Developed Thermal Insulation Plasters with Natural Fibres	
J. Hroudová, M. Sedlmajer and J. Zach	212
Analysis of Suitability of Mortar Used for Reconstruction R. Pernicová and D. Dobiáš	218
Effect of Freeze/Thaw Cycles on the Physical Properties of Selected Building Stones Z. Pavlík, J. Fořt, M. Pavlíková, J. Žumár and R. Černý	222
Brick as a Construction Material in the Modernization Process of the Ottoman Architecture A. Çiftçi and U. Yergün	228
Research on the Stability of the Paste-Like Silicone Impregnant W.J. Gu, Y. Li and J.K. Liu	234
Phase and Microstructural Characterization of Lime-MK Blended Mixes A. Gameiro, A.S. Silva, R. Veiga and A. Velosa	238
Experimental Analysis of Different Kinds of Sandstone for Reconstruction of Historical Masonry Z. Pavlík, J. Fořt, M. Pavlíková and R. Černý	244
Innovative Lime-Pozzolana Renders for Reconstruction of Historical Buildings E. Vejmelková, P. Máca, P. Konvalinka and R. Černý	248
The Effect of Salt Solutions in the Capillarity Absorption Coefficient of Red Brick Samples A.S. Guimarães, J.M.P.Q. Delgado, T. Rego and V.P. de Freitas	252
Increase Water Resistance Decorative Coatings on the Basis of Calcareous Dry Building Mixtures	
V. Loganina, L.V. Makarova, R.V. Tarasov and K.A. Sergeeva	257

Impact Depth on Glass Surface Caused by Sand Particles S. Bouzid and Z. Azari	260
Hardened Properties of Lime Based Mortars Produced from Kaolin Wastes A.F.N. de Azerêdo, A.M.P. Carneiro, G.A. de Azeredo and M. Sardela	276
New Type of Lime Plaster with Pozzolana Admixture for Renewal of Historical Buildings Z. Pavlík, M. Pavlíková, J. Maděra and R. Černý	291
Stone Monuments Consolidation with Nanomaterials R.M. Ion, R.C. Fierăscu, I. Fierăscu, I.R. Bunghez, M.L. Ion, D. Caruțiu-Turcanu, S. Teodorescu and V. Rădițoiu	295
Characterization of Building Stones Involved in Historical Masonry Z. Pavlík, E. Vejmelková, M. Pavlíková, M. Keppert and R. Černý	301
Destruction of Monuments' Materials by Organic Acids – Micromycetes Metabolites D. Shlychkova, S. Starsev and D. Vlasov	305
The Experimental Study on Consolidation of RTV for Wet-Area Earthen Ruins in Southwest China Y. Wu	312
Differences in the Properties of Arenaceous Marlstones from Different Quarries	
E. Vejmelková, M. Čáchová, D. Koňáková, M. Keppert, P. Reiterman and R. Černý	316
Simulation and Measurement of Hygrothermal Behaviour of Newly Developed Plasters J. Hroudová, M. Sedlmajer, V. Novák and J. Zach	321
Retrofitting Effect of Unreinforced Masonry Walls Using FRPs B.I. Bae, B.K. Park, H.K. Choi and C.S. Choi	329
Bond Behavior of Standard and Reinforced Anchorage between CFRP Sheet and Natural Calcareous Stone	
L. Anania, A. Badalà and G. D'Agata	333
On Problems of Mechanical Properties of Structural Steel in Load-Carrying Structure of Historical Building Construction M. Karmazínová and J. Melcher	341
Lime-Based Materials and Practices for Surface Refitting of Cultural Heritage	
S.B. Dai, J.H. Wang, Y. Hu and D.B. Zhang Remediation of Historic Buildings and Patrimony by Bacterially Induced Mineralization	347
P.H. Li and W.J. Qu Air Lime Mortars: The Influence of Calcareous Aggregate and Filler Addition	353
A. Fragata and R. Veiga Application of Chemicals in the Restoration of Monuments	359
W.Ž. Huang	365
Recycled-Aggregate Bedding Mortars for Repair of Historical Buildings V. Corinaldesi	369
An Experimental Study of Pig Blood–Lime Mortar Used on Ancient Architecture in China P. Zhao, D.Q. Xie, G.Y. Li and Y.S. Zhang	377
Application of Silicone TQ Resin Reinforced RTV Silicone Rubber in Architecture Y. Li, W.J. Gu and D.Y. Yang	381
Composition Identification of Typical Decorative Textiles in Tibetan Historical Buildings by	301
Burning Test and Projection Microscope Test F. You, F. Yang and M. Ren	386
Chapter 3: Problems of Rising Damp, Moisture and Salt Erosion	
The Rising Damp in Cultural Heritage: From Physical and Numerical Analyse to Practical	
Application J.M.P.Q. Delgado, A.S. Guimarães and V.P. de Freitas	393
Degradation Control of Walls with Rising Damp Problems A.S. Guimarães, J.M.P.Q. Delgado and V.P. de Freitas	442
Characterization of a Hygro-Regulated Wall Base Ventilation System for Treatment of	
Rising Damp A.S. Guimarães, J.M.P.Q. Delgado and V.P. de Freitas	448
Rising Damp: Optimization of the Wall Base Ventilation System A.S. Guimarães, J.M.P.Q. Delgado and V.P. de Freitas	454

The Effect of Shading Devices in Rising Damp Phenomenon of Historical Buildings J.M.P.Q. Delgado, A.S. Guimarães and V.P. de Freitas	460
Numerical Simulation of Rising Damp Phenomenon A.S. Guimarães, J.M.P.Q. Delgado and V.P. de Freitas	466
The Influence of some Physical Variables in the Capillarity Rise of Different Monolithic Walls	
J.M.P.Q. Delgado, A.S. Guimarães and V.P. de Freitas	472
Experimental Determination of Innovative Plaster Moisture Expansion J. Lukovičová, G. Pavlendová and S. Unčík	478
Storage Properties of Water-Solube Salts in Bastion Historical Brick R. Pernicová	482
Determination of Salt Transport Properties of Sandstone: A Combined Experimental/Computational Approach Z. Pavlík, M. Pavlíková and R. Černý	486
A Contribution to the Treatment of Salt Damage in Historical Buildings I. Antepara, I. Medved', J. Žumár and R. Černý	491
Non-Destructive Prospection of Ancient Steam Bathes Covered with Tadelakt — First Preliminary Comparison of Hammam Kasbah des Caids of Tamnougalt and Hammam Kasbah of Taourirt, Morocco	
B. Wolff, U. Diederichs and H. Ait el Caid	497
Chapter 4: Seismic Assessment and Technologies of Seismic Protection	
The Conservation of Earthen Architectural Heritage in Seismic Areas J. Vargas Neumann	509
Seismic Out-of-Plane Assessment of Podesta Palace in Mantua (Italy) S. Degli Abbati, S. Cattari, I. Marassi and S. Lagomarsino	522
Distributed Structural Monitoring for a Smart City in a Seismic Area V. Gattulli, F. Potenza, F. Graziosi, F. Federici, A. Colarieti and M. Faccio	531
Finite Element Analyses of Aghjots Monastery Taking into Account Seismic Action L. Karapetyan	544
An Innovative Approach to Assess Seismic Safety of Historical Centres I. Vanzi, S. Biondi, N. Cataldo and C. Sulpizio	549
The Seismic Assessment of the Curia in the Roman Forum through Simplified Models S. Podestà and S. Parodi	558
Behavior of the Leaning Tower of Pisa: Insights on Seismic Input and Soil-Structure	
Interaction R. Bartelletti, G. Fiorentino, G. Lanzo, D. Lavorato, G.C. Marano, G. Monti, C. Nuti, G. Quaranta, F. Sabetta and N. Squeglia	564
Dynamic Parameters of Pultruded GFRP Structures for Seismic Protection of Historical Building Heritage	20.
G. Boscato and S. Russo	573
Seismic Safety Assessment of the "Tekyeh Amir Chakhmagh" by Simplified Kinematic Limit Analysis S. P. Pashanaiati and C. Malina	582
S.R. Pashanejati and C. Molins Seismic Assessment of the Superstructure of the Naghareh Khaneh Edifice after Base	382
Isolation by Simplified Kinematic Limit Analysis M. Golabchi, P. Homami and S.R. Pashanejati	588
Seismic Assessment of Monastery of Stoudios (Imrahor Mosque) in Istanbul B. Kucukdogan, J. Kubin and A.I. Unay	594
The Intervention of Earthen Heritage in Seismic Areas and the Conservation Charters J. Vargas Neumann, M. Blondet and C. Iwaki	600
Seismic Analysis for the Structural Retrofit of "Palazzo della Civiltà Italiana" in Rome EUR, Italy	
T. Trombetti, C. Ceccoli, G. Gasparini and S. Silvestri	608
Seismic Vulnerability of Historical Structures: Damage State of the Abruzzo (Italy) Churches in the Sequence of the April 2009 Earthquake B. Silva, C.Q. Costa, F. Da Porto, M.R. Valluzzi and C. Modena	614

Investigation on Seismic Properties of Load-Bearing Masonry Walls in Chinese Historical Buildings	
B. Peng, W.D. Liu and W.B. Yang	620
Seismic Assessment of a Historical Masonry Building C.H. Huang, S.H. Yin and S. Chou	625
Design of the Seismic Upgrading of the Tambour of the S. Nicolò's Church in Catania with the DIS-CAM System	
M. Di Croce, F.C. Ponzo and M. Dolce	629
Performance-Based Seismic Evaluation of Historical Buildings W. Cui, W.P. Zhang and X.L. Gu	635
System Based Seismic Strengthening Design Analysis for a Historic Building L. Wang, Y.P. Peng, X.L. Gu, W. Cui and W.P. Zhang	641
Temporary Preventive Seismic Reinforcements on Historic Churches: Numerical Modeling of San Frediano in Pisa A. de Falco, L. Giresini and M. Sassu	647
Cultural Heritage Buildings and the Abruzzo Earthquake: Performance and Post- Earthquake Actions	(51
C. Modena, F. Da Porto, C. Filippo, M. Munari and E. Simonato Collapse Mechanisms due to Earthquake in the Structural Typologies of Historic	651
Constructions: The Case of Mirandola G. Boscato, A. Dal Cin and S. Russo	666
Mechanical and Mineralogical Characterization of Mortar in Masonry Buildings Damaged by the 20-29 th May Earthquake in Emilia E. Galli, M. Savoia, C. Colla and D. Ferretti	673
Adobe and Effect of Earthquake on Adobe Structure M. Najinassajfar and A. Vahidi	681
The S. Marco Church in L'Aquila: Provisional Interventions after the 2009 Abruzzo	
Earthquake M. Carraro, T. Ghedina, A. De Sabbata, C. Modena, F. Casarin and D.M. Benetta	685
Damage Assessment of Historic Buildings Hit by Earthquake G. Boscato and A. Dal Cin	691
Anime Sante Church's Dome After 2009 L'Aquila Earthquake, Monitoring and Strengthening Approaches	
G. Boscato, D. Rocchi and S. Russo	698
Numerical Analysis of Rigid Body Behaviour A. Gesualdo, A. Iannuzzo, M.T. Guadagnuolo, A. Guerriero, M. Monaco and M.T. Savino	717
A Discrete Element for Modeling Masonry Vaults I. Caliò, F. Cannizzaro and M. Marletta	725
First Evaluations on Structural Response of FRP Pultruded Applications Subjected to Seismic Actions	
G. Boscato	731
Chapter 5: Modeling, Assessment, Structural Analysis and Monitoring of Elements and Objects of Historic Structures	
Preventive Fire Risk Assessment of Italian Architectural Heritage: An Index Based Approach	
A. Arborea, G. Mossa and G. Cucurachi	739
The Crack Pattern in Brunelleschi's Dome in Florence: Damage Evolution from Historical to Modern Monitoring System Analysis	716
F. Ottoni, E. Coïsson and C. Blasi Strength Performance of Unreinforced Brick Masonry Walls under Flexo-Compression	746
Load. Analytical Methods E. Bernat-Maso and L. Gil	758
Effects in Monitoring of the Thermal Moisture Regime of Cultural Objects Located in	
Different Climate Conditions L. Kubičár, J. Hudec, D. Fidríková, P. Dieška and M. Vitkovič	764

A Self-Heating Approach to Characterize Anisotropy Effects in Fatigue Behaviour: Application to a Nineteenth Century Puddled Iron from a French Railway Bridge L. Gallegos Mayorga, S. Sire, S. Calloch, S. Yang, L. Dieleman and J.L. Martin	770
Numerical Modelling of Historical Masonry Structures J. Brozovsky, M. Jašek, L. Mynarzova and M. Maluchová	777
Numerical Simulation of Air Channel in Church Gemerský Jablonec L. Ťažký and A. Sedláková	783
Material Testing of Natural Stones Used in Historical Buildings Based on Scanning Electron Microscopy and Nanoindentation	
P. Koudelka, D. Kytýř, V. Koudelková, J. Lukeš, T. Doktor and J. Valach	787
Building Vulnerability: An Interdisciplinary Concept P. Vlamos, V. Chrissikopoulos and M. Psiha	791
A Dynamic Identification of a Historical Building Using Accelerometers with Interface Modules and a Digital Synchronization Method L. Spedicato, I. Armeni, N.I. Giannoccaro, M. Avlonitis and S. Papavlasopoulos	796
Repair and Health Monitoring for Historical Structures M.H. Maleki Tabrizi	804
A Wireless Sensor Network Innovative Architecture for Ambient Vibrations Structural	
Monitoring K. Oikonomou, G. Koufoudakis, E. Kavvadia and V. Chrissikopoulos	809
Synchronization Issues in an Innovative Wireless Sensor Network Architecture Monitoring	007
Ambient Vibrations in Historical Buildings G. Koufoudakis, N. Skiadopoulos, E. Magkos and K. Oikonomou	816
Hearing the Buildings: Smart Monitoring through Advanced Sonification Approaches A. Floros, E. Vlamou and V. Chrissikopoulos	822
CFD Model of an Underfloor Air Cavity Created from Special Fittings and its Verification Using a Laboratory Model T. Renčko and A. Sedláková	828
The Occurrence of Cyanobacteria and Green Algae on Facades of Historical Sacral	020
Buildings R. Wasserbauer, Z. Rácová, I. Loušová and M. Lecák	834
Historical Analysis and Structural Monitoring Cases – Studies for an Integrated Approach L. Balboni, P. Corradini, D. Del Curto and L. Valisi	838
Numerical Analysis of Tunnelling Effects on Masonry Buildings: The Influence of Tunnel	050
Location on Damage Assessment G. Giardina, M.A.N. Hendriks and J.G. Rots	844
Pathology of the Katholikon of Hosios Loukas Monastery and Preliminary Structural Analysis	
A. Miltiadou-Fezans, E. Vintzileou and N. Delinikolas	850
Measurement and Calculation of Ventilation in the Floor of the Brewery Žirovnice J. Jurka and J. Škramlík	856
Long-Term Reliability of Historical Monuments Built with Low Quality Sandstone E. Verstrynge, L. Schueremans, D. Van Gemert and E. Bourel	860
Static Monitoring and Non-Destructive Test of a Historic Damaged Palace G. Boscato and A. Dal Cin	966
Structural Strengthening of the Portico of the Santa Maria Dei Servi Church in Bologna S. Baraccani, M. Palermo, G. Gasparini, S. Silvestri, T. Trombetti and G. Dallavalle	866 870
Prince of Wales Fort: Structural Wall Analysis A. Isfeld and N. Shrive	877
Statistical Time Series Analysis of Crack Movements at Bayon Main Tower, Cambodia S. Yamada, M. Araya, M. Fukuda and Y. Iwasaki	883
Stability Analysis of Monument: A Case Study–Safdarjung Tomb A. Ahmad and K. Moin	889
Behavior of the Leaning Tower of Pisa: Analysis of Experimental Data from Structural	009
Dynamic Monitoring R. Bartelletti, G. Fiorentino, G. Lanzo, D. Lavorato, G.C. Marano, G. Monti, C. Nuti, G. Quaranta and N. Squeglia	897
Structural Analysis of the Bell Tower of the Basilica De La Merced of Lima	07/
H.E. Torres Peceros	906

Structural Analysis of the "3Ponti" of Comacchio (Ferrara, Italy) M. Pizzolato, M. Monti, P. Pigozzi and A. Tralli	911
Structural Assessment of the Vaulted Masonry Ice Storage Glacières Royales (1874) in Brussels	
A. Hellebois, D. De Wolf and M. Provost	917
Investigation and Analysis of the Cultural Buildings of Industry Remains in Yanbian M. Wei and Z. Zheng	923
Assessment Tool for Refurbishments reSBToolCZ Emphasising Cultural-Historical Buildings	
S. Mancik and J. Růžička	929
Investigating Interior Changes in Historical Building by Computational Modeling and Determination Critical Places for Structural Conservation J. Souček and P. Tichá	933
Introduction to Problems of Candle Combustion in Buildings J. Souček	937
Eye Bars - Pins Connections E. Petzek, A. Butiscă and L. Toma	946
Analysis on the Building Material of the Traditional Copper Hall from the Taishan Mountain, Using XRF and GIS	
J.W. Zhang	954
Examples of the Use of Non-Invasive Techniques for the Evaluation of Stone Decay in Portugal A. Dionísio, E. Martinho, C. Grangeia and F. Almeida	959
Preliminary Observations on the Structural Condition of a Byzantine Monument in Historic	939
Peninsula of Istanbul: Pantokrator Church U. Almaç	967
Settlement Induced Damage Modelling of Historical Buildings: The Bell Tower of the	
"Basilica dei Frari" in Venice F. Lorenzoni, M.R. Valluzzi, C. Modena, E. Simonato, F. Casarin and A. Lionello	973
Investigation of the Rail-Induced Vibrations on a Masonry Historical Building A. Erkal, D. Laefer, P. Fanning, E. Durukal, U. Hancilar and Y. Kaya	979
Dynamic Behavior of a Historical Building D. Rinaldis, P. Clemente and G. Buffarini	985
Study on Relationship between Elastic Wave Profile and Stones' Condition in Angkor Monument	
S. Tachino, S. Yamada, S. Sakurai, M. Araya and Y. Iwasaki	991
Analysis on the Western-Style Structural System of Zizhulin Church Q. Liu, J. Xie and A.X. Ge	997
Strengthening Proposals for the Trigonio Tower at the City Walls of Thessaloniki	
V. Delizisi, M. Axiotidou, I.N. Doudoumis and C. Ignatakis	1003
Comparison of Two Different Underfloor Ventilation Systems Using CFD T. Renčko and A. Sedláková	1009
Modeling Interior Environment of Historical Building and Determination of Critical Places for Application of Nanotextiles Protection	
J. Souček and P. Tichá	1014
Regional Policies for Sustainability in the Mediterranean Countries: The Role of a Proper HVAC System Maintenance in Museums A. Galatioto, S. Pitruzzella, G. Scaccianoce and D. Milone	1018
Preservation, Safeguard and Valorization of Masonry Decorations in the Architectural	1010
Historical Heritage of Piedmont (Italy) A. Carpinteri, S. Invernizzi, G. Lacidogna and A. Manuello	1023
Parametric Modeling of Typical Chinese Traditional Buildings on the Basis of 3DSMax	
Script W. Wang and B.Y. Xie	1029
Progressive Collapse Evaluation for Historic Building Structures F. Lin, Y. Wang, X.L. Gu and X.Y. Zhao	1033
Structural Analysis and Consolidation Strategy of the Historic Mediceo Aqueduct in Pisa	
(Italy) M. Andreini, A. de Falco, L. Giresini and M. Sassu	1040

Strategy of Research on the Application of Three-Dimensional Information about Historical Building Heritage in Cold Region R. Han, J. Lv and B. Li	1044
Research on the Deconstruction and Application of "Xinya Style Architecture " Based on Building Information Modeling Technology	1044
R. Han, J. Lv and B. Li	1048
SHM of Historic Damaged Churches G. Boscato, A. Dal Cin, S. Russo and F. Sciarretta	1052
Durability Research on Masonry Structures of Historical Buildings in Xi'an Beilin Museum Z.P. Dong, C.X. Hou, X.G. Liu and Q.L. Wang	1060
Selected Non-Destructive Methods Suitable for Evaluation of Roofing Slate M. Vavro, K. Souček, T. Daněk and L. Staš	1067
Hagios Gregorios Theologos Church in Cappadocia B. Çelebioğlu and S. Limoncu	1075
Chapter 6: Technologies of Restoration and Preservation	
New Resolution for Historic Building Conservation by Building Moving Technology X.L. Lu, W.S. Lu and X. Zhang	1083
The Complexity and the Logic Behind Historical Buildings: The Case-Study of Palazzo del Podestà in Mantova, Italy M. Cofani, V. Frignani and A. Landi	1090
Procedures and Techniques Used to Increase the Durability of Weak Masonries with Clay	1070
Mortars D. Covatariu, M. Budescu, N. Țăranu, I. Lungu and I.O. Toma	1096
Analysis of Building Stone of the Medieval Historical Building M. Balintova, A. Eštoková, A. Sicakova, M. Holub and E. Singovszka	1104
Surface Treatments for Historical Constructions Using Nanotechnology M. Colonna, C. Gentilini, F. Praticò and F. Ubertini	1108
Comparison between Methods of Biological Crust Removal on Granite S. Pozo, C. Montojo, T. Rivas, A.J. López-Díaz, M.P. Fiorucci and M.E. López de Silanes	1117
The Application of BIM in the Restoration of Historical Buildings Y. Li, K. Dong and G.F. Li	1126
Value-Based Architectural Conservation Practice as an Alternative Solution to Sustainability Problems	
P. Praptidita Suratman and Denny Differences in the Design of Underfloor Air Cavities	1135
T. Renčko and A. Sedláková	1139
Repairing of Damaged Stone in Monuments and Stone Buildings A. Teixeira-Pinto	1145
Study on the New Green Technology in Protection and Renovation of Historical Buildings' Structure	
H.X. Yu and L. Yan	1155
Restoration and Strengthening of a Historical Structure in Antalya - Turkey A. Koçak and Z. Kilit	1160
Historical Architectures Renovation Strategy under the Guidance of the Ecologic Concept J. Zhang and Y.H. Zou	1170
Historical Heritage: A Study to Conservation C. Borges, A.S. Silva, R. Veiga and G. Borsoi	1177
Strengthening Strategies of a Historical Masonry Construction R.S. Olivito, A. Tedesco, R. Codispoti and G. Spadea	1184
Efficiency of CFRP Strengthening of Arches Tested by Failure of Historical Building after the Inappropriate Repair Intervention K. Flaga and A. Kwiecień	1192
The Building Decorative Material Renewal Design Based on the "3R" Principles - Taking Pingjiang Historical Street of Suzhou as an Example	
X. Cheng, R. Han and Z. Zhu	1198

The Influence of Faulty 19 th Century Technical Solutions on a Work of 18 th Century Rafter Framing as Exemplified by Church in Nowy Kościół in Lower-Silesia, Poland - Case Study K. Ałykow and M. Napiórkowska-Ałykow	1202
Retrofitting and Strengthening Design for the Former Yihe Spinner Factory in Shanghai Y. Ouyang and Y. Yi	1210
Restoration of the Chapel of Padre Faria in Ouro Preto, MG - Brazil M.R.O. De Marco and B.T. De Oliveira	1215
Second World War Damages of the Architectural Heritage: St. Maria Del Popolo Agli Incurabili Church in Naples	
V. Russo, G.P. Lignola, E. Vassallo and A. Zinno	1220
Restoration of the Tsar-Bell Pedestal in the Moscow Kremlin A. Shilin, M. Zaitsev, A. Kirilenko and L. Fabijansky	1226
Protecting the Tangible and Intangible Heritage of Rani ki Vav: A Unique Subterranean Step Well in Gujarat T.L. Priya	1231
The Digital Protection of Minority Architectural Culture Heritage	
J. Song and H.M. Huang The Appropriate Fire Prevention Technology for Historic Buildings	1239
I.J. Wen and M.J. Lee	1242
Damaged and Healthy Ignimbrites from the Surroundings of Morelia, Mexico; Uses for Restoration of the Colonial Inheritance	
W. Martínez-Molina, E.M. Alonso Guzmán, H.L. Chávez-García, J.C. Arteaga-Arcos, A.A. Torres-Acosta, C.L. Gómez, J.A. Bedolla-Arroyo and F.A. Velasco-Ávalos	1248
Strengthening of Historical Masonry Buildings with Fiber Reinforced Polymers (FRP) A. Kheyroddin, M.H. Saghafi and S. Safakhah	1255
Stabilization and Strengthening the Foundation of the Two Entrance Gates of the Holy Shrine of Imam Reza (PBUH) P. Homami and M. Golabchi	1263
Role of the Geologists in the Process of Monuments Ashlar Masonry Repair K. Kovářová, J. Schröfel and S. Chamra	1269
Chapter 7: Technologies of Reconstruction, Conversion and Retrofitting	
Conversion of Industrial Hall Buildings M. Peřinková, M. Twrdá and L. Kolarčíková	1279
Preservation, Reconstruction or Conversion - Contemporary Challenge for Historic Urban Areas and Historic Buildings T. Bradaelki and B. Ulbanel, Bradaelka	1202
T. Bradecki and B. Uherek-Bradecka Reconstruction of Courtyards in Historical Buildings of Saint-Petersburg – Ways to	1283
Improve Quality of Interior Space V. Murgul	1290
Solar Power Supply in the System of Restoration and Reconstruction Remote Historic and Cultural Objects (on the Example of Montenegro) V. Murgul, N. Vatin and E. Aronova	1300
Energy Retrofit of Historical Buildings Based on Windowed Elements	
C. Guattari, G. Battista, L. Evangelisti, A. Fanchiotti and L. Santarpia Influence of Shading and Transparent Surfaces on Historical Building Energy Retrofit	1307
L. Evangelisti, C. Guattari, G. Battista and L. Santarpia	1312
Heritage Earth Construction and Hygrothermal Comfort: The Challenge of Rebuilding in Central Chile C.J. Whitman	1317
The Use of Decentralized Ventilation Systems with Heat Recovery in the Historical	-21/
Buildings of St. Petersburg V. Murgul, D. Vuksanovic, N. Vatin and V. Pukhkal	1327
High-Tech Solutions for Building Retrofit: Investigation of Window Systems with Vacuum	
Glazing O. Proskurnina, U. Pont, M. Schuss, C. Sustr, E. Heiduk, P. Schober and A. Mahdavi	1334

Autonomous Systems of Solar Energy Supply under the Weather Conditions of Montenegro V. Murgul, N. Vatin and E. Aronova	1342
Reflection on Modernization of Historic Religious Architecture - Case Study: The Roman Catholic Parish Church, Rajec in Slovakia	1250
B. Polomová and A. Vargová	1350
Possibilities of Simulations in the Planning of the Retrofit of Historical Double Skin Windows D. Bakonyi and G. Becker	1356
A Study to Interior Design Project Management Guideline Using on Historical Building Renovation	
W. Zhang and Y.E. Li	1362
Analysing Buildings from Context to Detail in Time: The ABCD Research Method Case Study: Friesland Provincial Library in Leeuwarden H. Zijlstra	1366
The Echo (Jeka) Pavilion in Forest-Park Maksimir Zagreb - Restoration and Health Monitoring	
M. Hasan, R. Despot, J. Trajković, A.O. Rapp, C. Brischke and C.R. Welzbacher	1372
Exploring Conservation and Development Strategies for Architectural HeritageA Case Study from Paris Hotel in Kaiping, Guangdong J.H.T. Selia	1378
Retrofitting and Moving Protection for Historical Buildings in Jinan City	
X. Zhang, S.B. Li and T. Liu	1384
Development of the Ventilation System in Historical Buildings of St. Petersburg V. Murgul, D. Vuksanovic, V. Pukhkal and N. Vatin	1390
Structural Restoration and Adaptation to Modern Architecture of the Baroque Oppersdorf Palace, Wrocław, Poland	
P. Berkowski, G. Dmochowski, M.Y. Minch and J. Szołomicki	1395
Revitalization of Historical Building in Wrocław's City Centre, Poland P. Berkowski, G. Dmochowski, M.Y. Minch and J. Szołomicki	1400
Revitalization as the Principle of Architectural Heritage Protection – Case Study of Serbia and Russia M. Penić, V. Murgul and N. Vatin	1406
, ,	1400
Thermal Insulation Features of Residential Historical Buildings in the Case of Saint-Petersburg V. Murgul, V. Pukhkal and N. Vatin	1413
Energy-Efficient Modernization of the Nobel's Mansion in Saint Petersburg: Solar Energy	
Supply Potential E. Aronova, Ž. Radovanović, V. Murgul, N. Vatin and M. Shvarts	1422
The Application of Transparency in Renovation of Historical Building	1722
S.Y. Zhu and B.Q. Zhai	1429
New Structures for Transparent Roofs E. Vojteková, O. Ivánková and L. Konecna	1434
Adaptation of the Ruin of Outbuilding next to Classicist Manor-House in Opatová -	
Lucenec T. Varga, P. Pauliny and R. Ingeli	1438
Chapter 8: Architectural Heritage and Process of Urban and Rural Planning	
Research on Protection of Rural Historical Building and Development of Villages Individual Style	
S.J. Xing	1447
Agglomeration and Continue of Pieces of Historical Buildings F. Xu, Y. Tang and O. Hao	1452
A Brief Discussion on Landmark Building Y. Zhang	1458

Statements of Historical Memories - The Detail Planning and Design of Zhang Xiangwen's Former Residence J.H. Hao, F. Zhou and E.D. Liu	1462
Analyzing the Quality of New Developments in Historical Monuments M. Heidari Moghadam and F. Shahsavari	1468
The Historical City between Past and Future. Is the Center becoming Peripheral? A. Di Paola	1483
Architectural Conservation and Cultural Inclusion - The Applicative Case of Motta San Giovanni (Reggio Calabria-Italy) and its Romanian Community A. Bianco and V. Triolo	1487
The Characteristic and Protection Analysis on the Renmin Street - The Historical Axis of Changchun	1.402
L.M. Bai and J.M. Hou The Problems of Preserving Zones of Monuments in Urban Structure and Natural Environment in Republic of Armenia L. Khachikyan	1492 1496
The Culture Memory of the Times — In Urban Redevelopment Should Strengthen the Historical Building Protection W. Mo and Y.Q. Wang	1502
Explore on Digital Restoration of Historic Buildings in Colleges Based on the BIM Concept - As the Example of Jilin Architecture and Civil Engineering Institute Hong Qi Campus R. Han, Y.H. An and X.Y. Xie	1506
Study on Cultural Characteristics of Qingdao's Historical Buildings Built in German Occupation Period P.F. Zhao and B. Tao	1512
Exploration of Height Control in Urban Historical & Culture Heritage Protection Area- Take Example of Qu Jiang New District of Xi'an H. Xie and Q.H. Zhou	1516
On Strict Protection and the Sustainable Use of Modern Historical Building in Mount Lu L.R. Zou and X.Q. Li	1522
Research on the Diversified Planning of Historic and Cultural Towns M.C. Tian, K.Z. Jia and A.H. Xie	1526
Research on the Protection of Historic Building Features in the Reconstruction of the Old City Y. Peng	1531
	1331
Chapter 9: Related Topics	
Becoming Unsafe Overnight: Managing Historic Buildings as Building Regulations and Standards Change P. Phillips	1537
A Review on Prof. Liang Sicheng's Thought and Practice of Heritage Conservation T. Yao and Q. Cai	1544
Considering Ephemeral Monuments: Towards a Greener Architectural Theory R. Budi Santosa, J. Prijotomo and M. Rachmawati	1548
The Theory and Practice of Restoration in England in the Second Half of the 19 th Century: The Work of George E. Street F. López-Ulloa	1554
Construction and Decorative Style of Monument Architecture in Huizhou T. Xie and C.Y. Liu	1560
Neogothic Public and Industrial Buildings in the Russian Empire XIX Century I. Yamshanov, V. Goryunov, V. Murgul and N. Vatin	1564