

Table of Contents

Preface, Committees, Organizers, Endorsers and Sponsors

Chapter 1: Assessment and Conservation

Experimental Values of Wood Strength in Bending between the 17th and the 18th Century C. Tardini	3
Considering the Role of Wood and Timber Roof in Persepolis Architecture A. Davoodi and A. Davoodi	11
The Influence of Biological Factors on the Health of Timber Structures on 11th to 14th Century AD in Yazd S.R. Moghaddam, S. Poormohamadi, M. Saffar and F. Esfahanipour	19
Failures of the Listed Wooden Buildings in Istanbul A.O. Kuruscu and G. Arun	26
A Symbolic Wooden Building in Istanbul: The Amcazade Huseyin Pasha Reception Hall/Divanhane A. Erdem and Ö. Gürsel	34
A Study on Timber Structural Elements of a Traditional Turkish House O. Yilmaz Karaman and M. Tanac Zeren	42
Traditional Seismic Construction Technology of the Turkish House 'Konak', Concentration of the Case Study 'Saraclar Sehir House' in Safranbolu A. Kerimcan	50
Typical Failures, Seismic Behavior and Safety of the “<i>Bourbon System</i>” with Timber Framing N. Ruggieri, G. Tampone and R. Zinno	58
Research and Development on the Database for Visualizing Invisible Parts of Wooden House in Japan H. Sumikura, S. Matsumura and K. Fujita	66
Architectural Structural Survey of Groups of Traditional Timber Houses in South Nias, Indonesia N. Sadaka, S. Hanazato, T. Hanazato, Y. Uekita, K. Nitto, K. Sato, K. Ono, S. Yoyok, P. Diananta and E. Pradipt	74
Static and Thermohygroscopic Analysis of a New Typology of Timber Framed Structure in Dolomites A. Polastri, S. Christofides and R. Tomasi	82
The Traditional Wooden House in Bucovina, a Model for Durability C.G. Corduban and A. Polastri	89
The Study of Timber Structures Based on <i>In Situ</i> Investigation E. Zamperini	97
How an Accurate Surface Observation Can Help in the Interpretation of an Ancient Timber Structure: The Example of the Valdese Church in Florence N. Macchioni, M. Mannucci and A. Todorow	105
XVIII Century Wooden Stretchers Structure Designed for Large Canvas and an Example of the Assessment Method K. Górecka, M. Skłodowski, P. Pawłowski, J. Szpor and H. Arendarski	113
Antique Wooden Floor Construction Solutions and the Possibilities of Using them in Reconstructions A. Rozanska, E. Sudol, J. Wierzbicki and A. Mazurek	119
Wooden Boards Arches Roofs in Late Nineteenth-Century Industrial Architecture: Conservation Problems M. Mattone	128

Chapter 2: Timber Grading

<i>In Situ</i> Evaluation of the Reference Properties of Structural Timber Members. Use of Available Tools and Information	
J.S. Machado	137
Effects of Beetle Attack on the Bending and Compression Strength Properties of Pine Wood	
H. Cruz and J.S. Machado	145
Prediction of Strength and Elasticity in Oak Beams on the Basis of External Wood Characteristics	
G. Riesco Muñoz and A. Remacha Gete	152
Mechanical and Fungicidal Properties of approximately 100 Years Old Oak, Beech and Spruce Wood Beams	
N. Thaler and M. Humar	159
Non-Destructive Tests and Bending Tests on Chestnut Structural Timber	
B. Faggiano, M.R. Grippa and B. Calderoni	167
Effectiveness and Subjectivity of Visual Inspection as a Method to Assess Bending Stiffness and Strength of Chestnut Elements	
H.S. Sousa, J.M. Branco and P.B. Lourenço	175
Juniper Structures in Western Mediterranean Vernacular Architecture: Ongoing Research	
J.R. Ruiz-Checa and V. Cristini	183
Strength Class Prediction of Sardinia Grown Timber by Means of Non Destructive Parameters	
G. Concu, B. de Nicolo, N. Trulli, M. Valdés and M. Fragiaco	191

Chapter 3: Assessment by Non-Destructive Methods and Survey Techniques

The Penetration Test to Evaluate Wood Decay after 20 Years Timber Structure Assessment Experience	
E. Giuriani, A. Marini, S. Cominelli and A. Gubana	201
<i>In Situ</i> Compression Stress-Deformation Measurements along the Timber Depth Profile	
M. Drdácý and M. Kloiber	209
<i>In Situ</i> Assessment Method of Wood Using Normalized Withdrawal Resistances of Metric-Screw Type Probes	
N. Yamaguchi	217
Selected Methods of Diagnosis of Historic Timber Structures – Principles and Possibilities of Assessment	
J. Jasieńko, T. Nowak and K. Hamrol	225
Application of Non-Destructive Techniques in the Inspection of the Wooden Roof of Historic Buildings: A Case Study	
M.J. Morales-Conde, C. Rodríguez-Liñán and P. Rubio de Hita	233
Investigation of Timber Members at the Marasyk Station in Prague by Non-Destructive Methods	
H. Hasnikova and P. Kuklík	243
<i>In Situ</i> Non-Destructive Examination of Timber Elements	
J. Pošta, J. Dolejs and L. Vitek	250
Nondestructive Evaluation of Timber Columns of a Capela Bridge in the State of São Paulo, Brazil	
F.S. Ferro, J.C. Pigozzo, D.H. de Almeida, F.H. Icimoto, L. Borges de Macedo, C. Calil Junior and F.A. Rocco Lahr	258
Experimental Investigations of Material Properties of Timber Utility Poles Using Various Material Testing Approaches	
R. Elsener, U. Dackermann, J.C. Li, B. Samali and K. Crews	265
Correlating Visual Grading with NTD Methods for Assessing Timber Condition in Historic Buildings	
V. Anagnostopoulou and A. Pournou	273
Microwave Reflectometric Tool for Non-Destructive Assessment of Decay on Timber Structures	
N. Macchioni, M. Mannucci, R. Olmi, S. Palanti and C. Riminesi	281

Development of Radar Apparatus for Scanning of Wooden-Wall to Evaluate Inner Structure and Bio-Degradation Non-Destructively Y. Fujii, Y. Fujiwara, Y. Yanase, T. Mori, T. Yoshimura, M. Nakajima, H. Tsusumi, M. Mori and H. Kurisaki	289
Nondestructive Characterization of and Defect Detection in Timber and Wood C. Sklarczyk, F. Porsch, B. Wolter, C. Boller and J.H. Kurz	295
Effect of Elastic Modulus and Poisson's Ratio on Guided Wave Dispersion Using Transversely Isotropic Material Modelling M. Subhani, J.C. Li, H. Gravenkamp and B. Samali	303
Ultrasonic Imaging of Defects in Building Elements Made from Timber M. Krause, K. Mayer, P.K. Chinta and U. Effner	312
Assessment of Timber Structures Using the X-Ray Technology S. Franke, B. Franke and F. Scharmacher	321
Non Destructive Characterization of Wooden Members Using near Infrared Spectroscopy A. Sandak, M. Riggio and J. Sandak	328
Approaches to the Moisture Content Monitoring Intimber Elements: Development of a Resistive Method T.A. N'Guyen, N. Angellier, S. Caré, L. Ulmet and F. Dubois	335
Development of a Methodology for the Visual Inspection of Engineered Wood Products and Metal Hangers in Residential Construction J.R. Loferski, J.C. Bouldin and D.P. Hindman	342
Terrestrial Laser Scanning and Settled Techniques: A Support to Detect Pathologies and Safety Conditions of Timber Structures C. Bertolini-Cestari, F. Chiabrando, S. Invernizzi, T. Marzi and A. Spanò	350

Chapter 4: Assessment by Testing and Modeling

Estimation of Load-Bearing Capacity and Stiffness of Timber Beams with Through-Thickness Cracks A.Y. Naychuk	361
Modulus of Elasticity and Bending Strength of Squared Timber with Wane of Spruce and Larch T. Schrentewein	369
Strength Properties of Chestnut Structural Timber with Wane M. Brunetti, M. Nocetti and P. Burato	377
Non-Destructive and Semi-Destructive Test Methods for Strength Determination of Aged Wood A. Kraler and W. Beikircher	385
The Influence of Routed Grooves on the Bending Behavior of Old Timber Beams A. Cavalli and M. Togni	393
Damage Assessment and Residual Service Life Estimation of Cracked Timber Beams J.W.G. van de Kuilen and W. Gard	402
Evaluation of the Load-Carrying Capacity in Bending of Large Cross Section "Pitch Pine" Beams in Standing Structures M.C.T. Vázquez, A. Soilán Cañas and D. Lorenzo Fouz	410
The SWORFISH Project Approach for Modeling Wood Material Modifications in Timber Structures J. Sandak, A. Sandak, M. Riggio, I. Santoni and D. Pauliny	418
Assessment of the Glue-Line Quality in Glued Laminated Timber Structures B. Franke, F. Scharmacher and A. Müller	424
Determination of the Stress Distribution in Timber Elements Reinforced with Self-Tapping Screws Using an Optical Metrology System M. Ayoubi and M. Trautz	432
Characterization of Wood Fracture Using Optical Full Field Methods O. Pop, F. Dubois, M. Méité and J. Absi	440
Near Infrared Spectroscopy as a Tool for Estimation of Mechanical Stresses in Wood J. Sandak, A. Sandak, D. Pauliny, V. Krasnoshlyk and O. Hagman	448

Stress Level Prediction in Axially-Loaded Timber Beams Using Resonance Frequency Analysis: A Pilot Study T. Lechner, S. Laux and D. Sandin	454
A Vibration-Based Approach for the Estimation of the Loss of Composite Action in Timber Composite Systems U. Dackermann, J.C. Li, R. Rijal and B. Samali	462
An Evaluation of the Seismic Performance of a Traditional Timber Building in Istanbul, Based on the Material Deterioration, with the Finite Elements Method H. Dişkaya and O. Ceylan	470
Seismic Analysis of a 2-Storey Log House J.M. Branco, P.B. Lourenço and C.A. Aranha	478
A New Method to Assess the Seismic Vulnerability of Existing Wood Frame Buildings C. Loss, M. Piazza and D. Zonta	486
In-Plane Assessment of Existing Timber Diaphragms in URM Buildings via Quasi-Static and Dynamic <i>In Situ</i> Tests I. Giongo, D. Dizhur, R. Tomasi and J.M. Ingham	495
Shaking Table Test of 1/30 Scale Model of Palasport in Bologna with Timber Shell Roof Structure L. Tashkov and L. Krstevska	503
Study and Analysis of XIV Century Timber Built-Up Beams in Verona G. Mirabella-Roberti and M. Bondanelli	511
Numerical Modelling of Historic Vaulted Timber Structures C.F. Ferreira, D. D'Ayala, J.L. Fernandez Cabo and R. Díez	517
Assessment of the Realistic Stiffness and Capacity of the Connections in Quincha Frames to Develop Numerical Models N. Quinn and D. D'Ayala	526

Chapter 5: Reinforcement and Treatment of Timber Elements

Bending Tests on Natural Fiber Reinforced Fir Wooden Elements A. Borri, M. Corradi and E. Speranzini	537
Bamboo Reinforced Glulam Beams: An Alternative to CFRP Reinforced Glulam Beams C. Echavarria, B. Echavarría and H. Cañola	545
Analysis of Wood Laminated Beams Reinforced by Natural Fibres N.T. Mascia and R.M. Mayer	553
Moisture and Temperature Influence on Biocomposites-to-Timber Bonding M.R. Valluzzi, F. Nardon, E. Garbin and M. Panizza	561
Durability of Wooden Member Reinforced by Carbon-Fiber T. Hojo	569
Wood Glass-Fiber Reinforced Polyester (GFRP) Hybrid Cross-Section Used to Improve the Structural Behavior of Timber Beams C.E. Lanivski and E. Decher	575
Restoration of Structural Timber Elements Using Epoxy Resin: Analysis of Mechanical Properties M. da Silva Bertolini, L.B. de Macedo, D.H. de Almeida, F.H. Icimoto and F.A. Rocco Lahr	582
The Repair of Timber Beams with Controlled-Debonding Steel Plates G. Metelli, E. Giuriani and E. Marchina	588
Reinforcement of Timber Beams with Prestressed Wires J.H.J. de Oliveira Negrão	596
Investigation on the Self-Tapping Screws Capability to Induce Internal Stress in Timber Elements I. Giongo, M. Piazza and R. Tomasi	604
Mechanical Evaluation of Timber Conservation Processes by Bending Tests D.F. Henriques, L. Nunes and J. de Brito	612
Microwaves as a Remedial Treatment of Wood A.M. Lluch, F. Vegas López-Manzanares, C. Mileto and M. Diodato	620

Chapter 6: Strengthening of Connections

Lateral Resisting Experiment of Prestressed-Tube Bolted Connection for Post-and-Beam Timber Construction	
M.J. He, Y. Zhao and R.L. Ma	631
Numerical Analysis of a Rigid Node of a Spatial Timber Frame Made of Structural Elements with Built-up Cross-Sections	
C.E. Lanivski, A. Secu and G.M. Atanasiu	639
Novel Nail-Like Wood Connectors	
M. Riggio, D. Pauliny, J. Sandak and A. Sandak	647

Chapter 7: Upgrading of Timber Structures

Reinforcement of Timber Floors-Transversal Load Distribution on Timber-Concrete Systems	
A.M.P.G. Dias, S.R.S. Monteiro and C.E.J. Martins	657
Lateral Load Bearing Behavior of Timber-Concrete Composite Constructions	
H. Kieslich and K. Holschemacher	665
Ultra-Thin Topping Upgrades for Improved Serviceability Performance	
J. Skinner, R. Harris, K. Paine, P. Walker and J. Bregulla	673
Experimental Characterization of Timber Floors Strengthened by in-Plane Improvement Techniques	
M.R. Valluzzi, E. Garbin, M. dalla Benetta and C. Modena	682
Optimization of Mechanical and Acoustic Performance of Timber Floors	
M.R. Valluzzi, A. di Bella and E. Garbin	690
Seismic Behaviour of Composite Panel Composed of Laminated Wood and Bearing Glass - Experimental Investigation	
L. Krstevska, L. Tashkov, V. Rajčić and R. Zarnic	698
Seismic Behaviour and Retrofitting of Timber Frame Walls	
E. Poletti and G. Vasconcelos	706
A Development of the Visco-Elastic Damper for Timber Structure and a Suggestion of the Technological Design Assistance System	
K. Kohara, T. Nomura and K. Koumoto	714
Development of Wood-Based Multi-Layer Systems in Existing Building Stock	
A. Fadaei, W. Winter, D. Stefanoudakis and K. Hollinsky	722
Selected Solutions for Rehabilitation of Wooden Structures: Some Portuguese Case Studies	
A.O. Feio, D. Félix, V.M. Cunha and J.S. Machado	731
Repairing a Medieval Door	
D. Yeomans, H. Harrison and A. Smith	739

Chapter 8: Monitoring

Long Term Monitoring of Timber Bridges - Assessment and Results	
B. Franke, S. Franke, A. Müller, M. Vogel, F. Scharmacher and T. Tannert	749
An On-Going Monitoring Project of a New Timber Structure	
F. Lanata	757
The Echo (Jeka) Pavilion in Forest-Park Maksimir Zagreb - Restoration and Health Monitoring	
M. Hasan, R. Despot, J. Trajković, A.O. Rapp, C. Brischke and C.R. Welzbacher	765
12 Years of Structural Health Assessment and Maintenance for the Glulam Timber Structure of the Mormanno Traffic Bridge in Calabria	
G. Bignotti	771
X-Lam Panels in Swimming-Pool Building – Monitoring the Environment and the Performance	
L. Jorge and A.M.P.G. Dias	779

A Numerical Approach for the Hygro-Thermal Monitoring of Timber Structures under Environmental Conditions	
A. Genoese, A. Genoese, S. Fortino and P. Hradil	786
A Multi Sensor Approach for Prediction of Weathering Effects on Exposed Timber Structures	
J. Sandak, A. Sandak, D. Pauliny, M. Riggio, S. Bonfa and S. Meglioli	794
Monitoring of Wood Decay by near Infrared Spectroscopy	
A. Sandak, S. Ferrari, J. Sandak, O. Allegretti, N. Terziev and M. Riggio	802
Influence of Fungi on the State of Preservation and on the Usage Prospects of Antique Wooden Floor from Manor Houses in South-Eastern Poland	
A. Boguslaw, A. Rozanska, A. Jankowska and J. Sandak	810
Changes in Swelling and Water Absorption of Wood Degraded by Brown Rot Fungi	
J. Frankl	818
Earthquake Response Monitoring and Structural Analysis of Traditional Japanese Timber Temple	
K. Fujita, E. Shin, A. Ibaraki and M. Sanuki	823

Chapter 9: Learning from Case Studies

The Royal Palace of Naples: Diagnosis, Assessment and Structural Restoration of Complex Roofing Timber Structures	
B. Faggiano, M.R. Grippa and F.M. Mazzolani	831
Condition Assessment of the Timber Structures of a Century-Old Industrial Building Using a Nondestructive Inspection Procedure	
X.P. Wang, M. Teder and J. Wacker	840
Diagnosis for the Conservation of Wooden Ceilings inside the Ducal Palace in Sabbioneta (Mantua, Italy)	
F. Augelli, A. Bordina and J. Migliavacca	849
The Structural Concept of the 16th Century Floors of the Ducal Palace in Sabbioneta (Mantua, Italy)	
F. Augelli, V. Nicola, F. Petracco and L.C. Ronchi	857
The Conservation and Strengthening Intervention on the Wooden Floors of the Ducal Palace in Sabbioneta (MN-Italy)	
F. Augelli	865
The Strengthening Design of the Wooden Floor Structures of the Ducal Palace in Sabbioneta (MN)-Italy	
F. Augelli and C. Amigoni	872
The Hidden Gem	
I. Andreescu, V.A. Gaivoronschi and M. Mosoarca	880
Problems Relating to Assessment, Repair and Restoration of Wooden Roof Structures in Historic Buildings, as Exemplified by Two Case Studies in Southern Poland	
D. Bajno, Ł. Bednarz and T. Nowak	888
Structural Analysis of Gothic Roof Trusses in View of their Conservation. Case Study of St. Paul's Cathedral, Liege (Belgium)	
L. Debailleux	895
The Influence of Faulty 19th Century Technical Solutions on a Work of 18th Century Rafter Framing as Exemplified by Church in Nowy Kosciół in Lower-Silesia, Poland - Case Study	
K. Ałykow and M. Napiórkowska-Ałykow	903
The Wooden Roof of <i>Banesa e Skendulate</i> in Gjirokastra, Albania: The Role of the Diagnostic Test Campaign in the Structural Safety Evaluation	
S. Podestà, F. Pompejano and G. Stagno	911
Reconstruction of the Technical Museum in Zagreb	
V. Rajčić, D. Čizmar and M. Stepinac	919
Learning from Case Studies: Timber Tower of Gospić Cathedral and Traditional Timber Church	
M. Stepinac, V. Rajčić and D. Čizmar	927
Wood Construction System of Traditional Edirne Houses	
I.S. Canitez and T. Canitez	935

An Evaluation of Restoration Practices of Traditional Wooden Houses in Edirne T. Canitez and I.S. Canitez	943
Preservation of the Large Timber Roof of the Porta Nuova Railway Station in Torino C. Bertolini-Cestari, S. Invernizzi, T. Marzi and S. Rolla	951
A Historical Large Span Timber Construction - Refurbishment of the Main Cupola of Vienna University of Technology S. Jaksch, A. Fadaï and W. Winter	959
The Ancient Timber Roofing Structures in Emilia-Romagna Region A. Marzo, G. Marghella and M. Indirli	968
Investigation about the Decay of the Timber Structure of an Ancient Wine Cellar in La Rioja (Spain) and Sanitation Proposal A. Lozano Martínez–Luengas, M. Guaita Fernández, D. Lorenzo Fouz and J. Benito Ayúcar	976
Building for the Sea Safeguarding Ashore. Brigs, Ships and Peote: A Complex Conservation S. Porello	983
Tramways, Draw Works and Flumes D. Porter and R.W. Anthony	990
Timber Structure Repair of an Emblematic Catalan Industrial Building with Wood Grafts and Epoxy Resins M. Vilches Casals, V. Rodríguez Trujillo and C. Labèrnia Badia	998
A Comparison between Evaluation and Restoration Methods for Old Wooden Beam and Glued Laminated Timber G. Cenci and S. Cenci	1006
Structural Performance Analysis and Repair Design of Wenxing Lounge Bridge Q. Chun and L.X. Sun	1014
Diagnostic Evaluation of Insect Attack on Existing Timber Structures: A Review of some Case Studies E. Feci, M. Mannucci and S. Palanti	1020
The World's Tallest Wooden Observatorion Tower. Design for Durability M. Lackner and M. Vodicka	1028

Chapter 10: Codes and Guidelines

Assessment, Reinforcement and Monitoring of Timber Structures – COST FP1101 B. Kasal	1037
RILEM TC "Reinforcement of Timber Elements in Existing Structures" T. Tannert, J.M. Branco and M. Riggio	1041
Developing an Understanding for Grading Timber in Existing Buildings R.W. Anthony	1049
Structural Reliability of Spanish Softwoods. A New Answer for an Old Problem M. Nevado	1056
A Peculiar Spanish Timber Floor, the "Revolton": A Diagnostic Example at the "Palacio del Marqués de Benicarló" M. Diodato, N. Macchioni, M. Brunetti, B. Pizzo, M. Nocetti, P. Burato, L. Sozzi, E. Pecoraro, F. Vegas López-Manzanares and C. Mileto	1064
Recommendations for Design in Preserving Historical Buildings with Wooden Structures' Roofs Â. do Valle, N. Biscaglia Pereira and S. Castello Branco Nappi	1072
Timber Roof Structures in Extreme Weather Conditions T. Pazlar	1080
Seismic Vulnerability of Timber Roof Structures: Classification Criteria M.A. Parisi, C. Chesi and C. Tardini	1088
Evaluation of Health Conditions of Wooden Structures of the Former Slave Quarters of Farm Santa Maria do Monjolinho, Located in the State of São Paulo, Brazil A.F. Campos, L.B. de Macedo, M.â.P. de Castroe Silva Bortolucci and F.A. Rocco Lahr	1096